



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
-		Ref:	CS/TP21008541/Gqc
MOHAMED IZWANDY BIN MOHAMED NOOR APPT BLK 269B YISHUN STREET 22 #04-553SINGAPORE 762269		Date:	16/08/2021
		Code:	TP2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	FBE 5897X	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	16/08/2021	
2. Vehicle Particulars & Condition			
Make & Model	c.c	0	
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/08/2021	Inspection Date	16/08/2021
Survey held at	SOON HIN BLK 1018 #01-342 YISHUN INDUSTRIAL PARK A . SINGAPORE 768760		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			