



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CS/TP21008541/Gqc
MOHAMED IZWANDY BIN MOHAMED NOOR APPT BLK 269B YISHUN STREET 22 #04-553SINGAPORE 762269			Date:	16/08/2021
			Code:	TP2
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	FBE 5897X	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	16/08/2021	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	01/08/2021	Inspection Date	16/08/2021
	Survey held at	SOON HIN BLK 1018 #01-342 YISHUN INDUSTRIAL PARK A . SINGAPORE 768760		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

30.08.2021 Andy said he had engage lawyer to submit claim.

So we may proceed to cancel his service. *Celine 22.10.2021*