

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLP 1900 U**

	Materials	Cost (\$)
1	Emblem Mivec Technology	30.00 — <i>nec</i>
2	Harness, RR bumper	84.00 — <i>Tn</i>
3	Clips (x13)	78.00 — <i>nec</i>
4	Camera, RR view	568.00 — <i>B/R</i>
5	Reinf, Gate pillar, RH	250.00 — <i>DD</i>
6	Grommet, Tail lamp (x3)	9.00 — <i>nec</i>
7	Grommet, Tail lamp (x3)	9.00 — <i>nec</i>
8	Muffler, Exhaust Main	582.00 — <i>BT</i>
9	Pipe, Exhaust, Ctr	1,832.00 — <i>BT</i>
10	Silencer, Floor (x2)	28.00 — <i>nec</i>

Total Materials 3,470.00

	Labour	Cost (\$)
1	Replace rear end panel	450.00 —
2	Repair rear floor panel	225.00 —
3	Replace RH rear taillamp panel	225.00 —
4	Respray on rear floor panel	350.00 —
5	Remove & replace rear exhaust muffler & centre exhaust pipe	400.00 —


Total Labour 1,650.00

Taxable amount 5,120.00
7% GST 358.40

Grand total **\$ 5,478.40**

Thank You.

Yours faithfully,


LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6565 1240 / 6567 5258