

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
Website: <http://www.millionauto.com> Email: wendy@millionauto.com
Tel: 6567 0817, 6264 9091 Fax: 6791 4716
Reg No: 317413/00-K GST Reg No: M90363176A

Reg No: 317413/00-K GST Reg No: M90363176A

L/S

WITHOUT PREJUDICE

ESTIMATE COST FOR REPAIR GBG8160H NISSAN NV350

Tail gate assy	/ DD		1,816.70	Nett	- nett
Tail gate outer garnish	x nn		535.70	N x	
Tail gate Emblem	- nec		79.90	N	- nett
Tail gate lock	- Tommed		287.10	N -	nett
Tail gate lock cover	x nn		54.20	N x	
Tail gate rubber	x nn		154.30	N x	
Tail gate autolock actuator	x nn		255.90	N +	
Rear bumper	/ DD		600.50	N -	nett
Rear bumper retainer	- BR		18.50	N -	nett
Rear bumper step panel	x nn		164.20	N x	
Rear end panel outer	+ nn		246.50	N x	
Rear bumper clips	- nec		42.50	N	25- nett
70km/h sticker	- nec		25.00	20-	nett
7 pax sticker	- nec		25.00	20-	nett
Windscreen sealant	- nec		60.00	40-	nett
To dismantle & assembly rear windscreen			190.00	120-	
To spray paint & putty affected area			780.00	400-	
To apply anti rust proofing on affected area			120.00	x	
To remove & refix reverse camera & check wiring			190.00	60-	
To remove & transfer tailgate mechanism		1030	18.00	50-	
Labour charge for panel baeting rear panel & affected parts			680.00	400-	
	= 3937.70				
	L 15-3150.16				
	= 3150				
		Sub total :	6,344.00		
		GST 7% :	444.08		
		Total :	<u>6,788.08</u>		