

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197403559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

360, Raffles Place
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 59205
Date Estimated : 13/08/2021
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Wong Man Ho
27 Fernvale Road. (S)797415
High Park Residences
#12-30
SINGAPORE 797415

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW2439E	WBATS720X09C29021	10/11/2020	X3 sDrive20i	12379

DESCRIPTIONVALUE

To replace rear bumper, boot lid including to knock out dented area caused by the accident

1275 2,550.00

To respray rear bumper and boot lid

1972 2,076.00

To carry out body cavity preservation.
(Per panel).

112 118.00

To remove and install rear windscreen glass to facilitate repair.

574.00

To conduct water leak tests.

75.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

574 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Sundries.

? 150.00

Total Labour 1: **6,428.00**DESCRIPTIONQTYPRICVALUE

# TRUNK LID	1	1,983.20	1,983.20
REAR BUMPER CARRIER	1	765.35	765.35
REAR BUMPER BOTTOM REINFORCEMENT	1	79.25	79.25
# Panel for bumper	1	208.45	208.45
Trim cover,	1	211.25	211.25
# REAR BUMPER PANEL PRIMED (X	1	1,563.20	1,563.20

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59205
Date Estimated : 13/08/2021
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW2439E	WBATS720X09C29021	10/11/2020	X3 sDrive20i	12379

DESCRIPTION	QTY	PRIC	VALUE
PLAQUE 82MM / n/c	1	71.95	71.95
LETTERING X3 / n/c	1	64.75	64.75
LETTERING S DRIVE 20i / n/c	1	97.15	97.15
BUMP STOP / n/c	10	3.20	32.00
# REAR WINDOW GREEN X	1	1,121.75	1,121.75
(DG) CLEANER R1 (100ML) / n/c	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / n/c	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) / n/c	1	27.85	27.85

Total Parts : 6,515.40

Steve CLKK) with P.L
6/9/21, 11.00am
P/P
5 Lys
My Bel sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,428.00
Parts	:	6,515.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	906.04
Grand Total	:	13,849.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **