

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0659/2021/ZK
DATE : 16-Aug-21
WIP : 39914

Justin.

\$9093.76.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 20/8/2021

YOUR INSURED VEH NO : SMW 1747 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM MUI PENG
ADDRESS : BLK 55 HUME AVENUE
#07-06
SINGAPORE 598752
TELEPHONE : HP +65 9624 8735
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900093585-02
VEHICLE NO : SDK 1237 Y
MODEL CODE : AUDI A5 2.0 SPORTBACK 2.0 TFSI
MODEL YEAR : 27/4/2019
ENGINE NO : CVK 078768
CHASSIS NO : WAUZZZF54KA036756
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Aug-21
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD OUTSIDE KK HOSPITAL

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED SIDE LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 1237 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE.	800.00	280
2	TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOR AND LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	3,200.00	1100
3	TO RESPRAY LHS FRONT DOOR, DOOR HANDLE, LHS REAR DOOR AND LHS SILL PANEL TRIM	3,500.00	1650
TOTAL LABOUR CHARGES SIDE		\$ 7,500.00	

Form with multiple sections for vehicle details, accident information, and repair estimates. The form is mostly blank with some faint text visible in the background.



TRANSPORT ACCIDENT INVESTIGATION BOARD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 1237 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	X
2	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZ CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	X
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	\$ 2,000.00	SSO
4	TO RENEW LHS REAR RIM AND CARRY OUT WHELL ALIGNMENT.	S/N \$ 280.00	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES (SIDE + REAR)		: \$ 11,932.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 1237 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH <i>Rep</i>	1	\$ 3,884.00	+	
2	FRONT DOOR SEAL - LH <i>Ken</i>	1	\$ 222.00	+	
3	FRONT DOOR BONDING <i>Ken</i>	1	\$ 49.00	+	
4	FRONT DOOR CLEANING SOULTION <i>Ken</i>	1	\$ 68.00	+	
5	FRONT DOOR APPLICATOR <i>3</i>	1	\$ 8.00	+	
6	FRONT DOOR CATCH - LH <i>Joel</i>	1	\$ 120.00	x	
7	FRONT DOOR TRIM - LH <i>Ken</i>	1	\$ 164.00	✓	130.80
8	REAR DOOR - LH <i>Detid</i>	1	\$ 3,884.00	✓	3107.20
9	RAER DOOR SEAL - LH <i>Ken</i>	1	\$ 222.00	✓	177.60
10	REAR DOOR BONDING <i>Ne Ne</i>	1	\$ 49.00	x	
11	REAR DOOR CLEANING SOULTION <i>Ne Ne</i>	1	\$ 68.00	x	
12	REAR DOOR APPLICATOR <i>Ne Ne</i>	1	\$ 8.00	x	
13	REAR DOOR ATTACHMENT PART <i>Ken</i>	1	\$ 129.00	+	
14	RAER DOOR CATCH <i>Pangd</i>	1	\$ 120.00	✓	96
15	SIDE MEMBER TRIM - LH <i>Rep</i>	1	\$ 826.00	+	104
16	SIDE MEMBER TRIM ATTACHMENT PART <i>Ken</i>	1	\$ 130.00	✓	169.6
17	ADHESIVE TAPES <i>Ken</i>	1	\$ 212.00	✓	1352
18	REAR ALUMINIUM RIM - LH <i>Ken</i>	1	\$ 1,690.00	✓	
19	SUNDRIES <i>Ken</i>		\$ 192.00	✓	4.56
TOTAL SPARE PARTS			\$ 12,045.00		
TOTAL LABOUR CHARGES			\$ 11,932.00		
GRAND TOTAL			\$ 23,977.00		

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6941 1183
EMAIL NORAH.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Li
20/08/21

we authorised, 06 days
S.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: