

Section A - Accident Details

Registration Number	SHB5217D
Case Reference Number	TAX/08/21/2020
Registration Date	30/11/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE KWANG HANN
Type of Accident	Head to Rear
Accident Date and Time	11/8/2021 9:55 AM
Accident Reported Date and Time	11/8/2021 2:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111846
Special Instruction to ARC, if any	TP/REAR PORTION /AIG - LKK
Prepared Date and Time	12/8/2021 1:58 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,296.00	\$300.00
Total Spare Part Cost	\$5,819.74	\$1,877.12
Total Other Cost	\$360.00	\$70.00
TOTAL COST	\$8,151.74	\$2,547.12 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	16/08/2021 3:15 PM	16/08/2021 3:42 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	resurvey before paint / part by part

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2108-0447	Invoice Number	
Quotation Date	30.08.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$871.50	0.00	\$0.00	Replace	Not Given
		6556547010	PATCH, SIDE PANEL REAR END, RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given
		65637-47060	LINER, REAR FENDER, RH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.30	25.00	\$16.95	Replace	Replace
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Check
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52591-47080	SEAL, RR BUMPER, RH	0.00	\$118.30	0.00	\$0.00	Replace	Check
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace
		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$22.00	0.00	\$0.00	Replace	Check
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1.00	\$39.00	25.00	\$29.25	Replace	Replace

X SVC
X SVC
X SVC
√ DE
X SVC
√ NEC
√ NEC
√ NEC
√ NEC
√ NEC
√ NEC
X SVC
X SVC
X SVC
√ NEC
√ DE
X SVC
√ SCR

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/08/2021

User ID : PohSuan

		58398-47050	COVER, REAR FLOOR UNDER , RH	0.00	\$175.10	0.00	\$0.00	Replace	Not Given	X SVC
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Not Given	X SVC
		81551-47481	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$339.60	0.00	\$0.00	Replace	Check	X SVC
		81497-47040	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X SVC
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Check	X SVC
		81580-47070	LAMP ASSY, REAR, RH	1.00	\$293.60	10.00	\$264.24	Replace	Replace	√ CRA
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	√ NEC
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X SVC
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Not Given	X SVC
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	100.00	\$0.00	Replace	Repair	R
		75403-48010	EMBLEM SUB-ASSY REAR	0.00	\$47.90	0.00	\$0.00	Replace	Not Given	X NN
		75441-47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$54.60	0.00	\$0.00	Replace	Not Given	X NN
		75442-47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$54.60	0.00	\$0.00	Replace	Not Given	X NN
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√ NEC
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√ NEC
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Check	X SVC
Total					\$6,160.30		\$1,191.92			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Not Given
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$913.60	25.00	\$685.20	Replace	Replace
Total					1,143.50		685.20		

1,877.12
+ 300.00
+ 370.00

2,547.12

X SVR
√ CRA