

1 of 2 ?	100%	Find Next
----------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21008604/Ktf3e2 Date: 04/10/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGP 7494U	Veh. Inspected	SLM 5962E	
Policy No.	29135698AT2	Coverage (\$)	0.00	
Claim No.	637520	Excess (\$)	0.00	
Assign From	KATHERINE WONG	Assign Date	17/08/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JMYSRCY1AGU006473	Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/08/2021	Inspection Date	23/08/2021	
Survey held at	176 Sin Ming Drive, #03-09			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				