Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 19 Aug 2021 Tan Kah Leong Date:

Preliminary Advice

Insured Vehicle No : GBC4492Y

TP Vehicle No : 14/08/2021 : SMM9776M Accident Date Make : TOYOTA C-HR HYBRID Assignment Date : 17/08/2021

Date of Inspection : 18/08/2021 Est. Duration of Repair : 5

Inspection At : JACK CARS ENTERPRISE PTE LTD (HQ)

61 UBI AVENUE 2, #01-20 AUTOMOBILE MEGAMART

SINGAPORE 408898

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,987.50
Revised Amount	:S\$	4,522.50
Check Items (Estimated)	:S\$	450.00
Total	:S\$	4,972.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

(The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.