



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:ONG KIAN THENG DERICK			Ref: CC4/ASM21008612/Tpa3q2 Date: 30/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJS 8493P	Veh. Inspected	SMV 115H	
Policy No.	GA498653	Coverage (\$)	0.00	
Claim No.	S1M03FPI	Excess (\$)	0.00	
Assign From		Assign Date	17/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI ACCENT	c.c	1368	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHCU41BTKU445148	Colour	RED	
Odometer	39950 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	FALKEN	6 mm	
L/H Front Tyre	175/70 R14	FALKEN	6 mm	
R/H Rear Tyre	175/70 R14	FALKEN	6 mm	
L/H Rear Tyre	175/70 R14	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/08/2021	Inspection Date	18/08/2021	
Survey held at	AP AUTOMOTIVE SERVICES PTE LTD 9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	