




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623			Ref: CS3/SMO21008621/Kvf3e2	
			Date: 25/08/2021	
			Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLM 3375M	Veh. Inspected	SLR 1679Z
	Policy No.	D21MTPV01003135	Coverage (\$)	0.00
	Claim No.	CMTD2102429/LOR	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	17/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU31222974	Colour	METALLIC BRONZE
	Odometer	63404 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	8 mm
	L/H Front Tyre	215/60 R16	DUNLOP	8 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5. General Information				
	Accident Date	14/08/2021	Inspect Date / Time	18/08/2021 (10:14 AM)
	Survey held at	ACCIDENT ASSIST SG 24 SIN MING LANE, #01-94, MIDVIEW CITY, SINGAPORE 573970		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/SMO21008621/Kvf3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.