



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21008628/Ags3q2 Date: 18/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7723R	Veh. Inspected	SJN 613P
	Policy No.	P2419140	Coverage (\$)	0.00
	Claim No.	S1M03FLN	Excess (\$)	0.00
	Assign From		Assign Date	17/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALPHARD	c.c	3456
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GGH208014223	Colour	BLACK
	Odometer	179778 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	PIRELLI	6 mm
	L/H Front Tyre	215/60 R17	PIRELLI	6 mm
	R/H Rear Tyre	215/60 R17	PIRELLI	6 mm
	L/H Rear Tyre	215/60 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/08/2021	Inspection Date	24/08/2021
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	