

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Lonpac Insurance Pte Ltd

Accident Date : 16.08.2021

Not Authorised
11 Days @
Reserving After Paim
Today

Third Party
Policy No: _____
Date: 17.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No SMQ4144Z Claiming Against Your Insured Soon Hin Foods Pte Ltd			
1pc	Front Door LH		Ry 1,135.00 ✓
1pc	Front Door Sticker		nc 36.00 ✓
1pc	Front Door Inner Lock		nc 275.00 X
1pc	Front Door Top Rubber Seal (Vertical)		nc 36.00 ✓
1pc	Front Door Lower Rubber Seal		nc 30.00 ✓
10pcs	Front Door Trim Board Clips	4.00	nc 40.00 X
1pc	Front Door Outer Handle		nc 282.00 ✓
1pc	Front Door Outer Handle End Cover		nc 65.00 ✓
1pc	Front Door Glass Regulator/Motor		499.00 ✓
1pc	Door "B" Pillar		Ry 1,030.00 ✓
1pc	Rear Door LH		Ry 977.00 ✓
1pc	Rear Door Outer Vertical Rubber Seal		nc 36.00 ✓
1pc	Rear Door Sticker		nc 33.50 ✓
1pc	Rear Door Weatherstrip		nc 99.00 ✓ 50h
1pc	Rear Door Top Rubber Seal (Vertical)		nc 36.00 ✓
1pc	Rear Door Lower Rubber Seal		nc 40.60 ✓
1pc	Rear Door Inner Lock		nc 220.00 ✓
1pc	Rear Door Trim Board		665.00 ✓
10pcs	Rear Door Trim Board Clips	4.00	16.00 ✓
1pc	Rear Door Glass Regulator/Motor		Ry 496.00 ✓
1pc	Rear Door Glass Guide		102.00 ✓
1pc	Rear Door Lower Chip Resistant Sticker		nc 40.00 ✓
1pc	Rear Door Lower Stopper		nc 11.00 ✓
1pc	Rear Door Arrestor		nc 60.00 X
1pc	Rear Door Top Hinge		Ry 50.00 ✓
1pc	Rear Door Lower Hinge		Ry 50.00 ✓
1pc	Rocker Panel Skirt LH		nc 392.00 ✓
10pcs	Rocker Panel Skirt Clips	4.00	nc 40.00 ✓
1pc	Rear Fender Protector LH		nc 180.00 ✓
10pcs	Rear Fender Protector Clips	4.00	nc 40.00 ✓
1pc	Rear Bumper Cover LH		nc 205.00 X
12pcs	Rear Bumper Clips	4.00	nc 48.00 X
1pc	Rear Bumper Wheel Bearing		nc 276.00 X
Less 20%			7,541.10
			1,508.22
			6,032.88
C/F			6,032.88

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Lonpac Insurance Pte Ltd

Third Party

Policy No: _____

17.08.2021

Date: _____

Accident Date : 16.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No SMQ4144Z Claiming Against Your Insured Soon Hin Foods Pte Ltd		
		B/F	6,032.88
	Front Door Inner Insulation		180.00 SN ?
	Sticker - Car Info		50.00 SN —
	Rear Door Inner Insulation		180.00 SN ?
	Rear Wheel Rim		850.00 SN X
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Dismantle / Transfer 2x Door Fittings / Ancillary Accessories	150.00	300.00 1201
	To Dismantle Rear Seat, Floor Carpet to Facilitate Repair		120.00 801
	To Dismantle / Refit Front Pax Seat Belt For Welding Pillar Panel, & Fault Code Erasure		150.00 ?
	To Supply Door Pillar Body Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 901
	To Dismantle / Hi Pressure Press / Replace Wheel Bearing		120.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 X
	To Conduct High Speed Balancing		80.00 X
	Labour Charge - Panel Beating, Repairing of Floor Panel, Rear Fender, Rocker Panel, Inner Panel etc. Cnt, Weld Door Pillar and Part Replacement		1,200.00 7001
	To Respray Affected Areas		1,300.00 8001
			10,882.88

KK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer