

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Adrian Lkk
Somp

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 11/08/2021

Estimated repair cost for vehicle no: SJM6540G TOYOTA WISH 1.8 S.A

CHASSIS: JTDER12W703001633 (2008)

18/08/2021

TP Somp

Veron

S/N	Qty	Items	U/price	Amount
1	1	BONNET <i>cracked.</i>	\$887.20	\$887.20 ✓
2	1	BONNET CHROME MOULDING <i>cracked.</i>	\$114.30	\$114.30 ✓
3	1	BONNET LOCK <i>new</i>	\$122.30	\$122.30 X
4	1	FRONT BUMPER <i>deformed.</i>	\$698.40	\$698.40 545.
5	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$475.90	\$475.90 X
6	1	FRONT BUMPER SPONGE <i>cracked.</i>	\$261.90	\$261.90 128.40
7	1	FRONT BUMPER SIDE RETAINER <i>new</i>	\$56.80	\$113.60 ✓
8	1	FRONT BUMPER LOWER GRILLE <i>new</i>	\$136.40	\$136.40 X.
9	2	FRONT BUMPER UNDER GARNISH COVER <i>new</i>	\$137.10	\$137.10 X
10	2	FRONT SUPPORT PANEL CENTER <i>Regis</i>	\$265.40	\$265.40 X
11	2	FRONT SUPOORT PANEL LH <i>Regis</i>	\$198.40	\$198.40 X.
12	1	FRONT SUPPORT PANEL TOP GARNISH <i>born</i>	\$194.70	\$194.70 ✓
13	1	FRONT BRACE PANEL <i>but.</i>	\$116.70	\$116.70 ✓
14	1	FRONT GRILLE <i>cracked</i>	\$298.40	\$298.40 155.80
15	1	AIR CON CONDENSER <i>new</i>	\$1,130.20	\$1,130.20 X.
16	1	LH FRONT HEADLAMP <i>cracked</i>	\$786.30	\$786.30 ✓

3042
2281.50

TOTAL : \$5,937.20
LESS 25 % \$1,484.30
SUB-TOTAL : \$4,452.90

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30.
2	1	AIR CON GAS <i>new</i>	\$100.00	\$100.00 X.

30

TOTAL: \$180.00

TOTAL PARTS: \$4,632.90

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & RENEW AIR CON CONDENSER.TOP UP GAS
- 5 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS

1180

\$1,200.00 500
~~\$1,000.00~~ 600
~~\$80.00~~ 30
 \$150.00 X
~~\$300.00~~ X 50

Subtotal :- \$2,730.00

Total:- \$7,362.90

total: 3481.50

2/s: 2.8K.

04 days

2.8K.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: