

Hui Zhen (LKK Auto)

From: Hui Zhen (LKK Auto)
Sent: Monday, 23 August 2021 10:40 am
To: SUR
Cc: SUR
Subject: OD SLZ 1651K / DOA: 01/08/2021

Dear Candy,

As instructed by our client , please proceed to repair the **insured vehicle SLZ 1651K, (Excess \$1,700).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Labour 1 not necessary. Replace centre top support panel does not required to take our condenser/radiator.

Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.

Before paint photos for all NEW Panels and Parts required after repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)