

E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

ESTIMATE

Date : 12th Nov 2021

M/s. Brillante Project Pte Ltd
2 Yishun Industrial St 1,
#07-10 Northpoint Bizhub
Singapore 768

Veh No : GBB 7276R
Make/Model : Mit Fuso
Chassis No : FB79BBA20087
Date of Acc : 14.08.21
TP Veh No : PC 861B

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Corner Panel LH	\$ R	438.00 ✓
2	1 pc	Frt Blinker Lamp LH	\$ CM	229.00 ✓
3	1 pc	Headlamp LH	\$ CM	669.00 ✓
4	1 pc	Frt Side Lamp LH	\$ CM	153.00 ✓
5	1 pc	Frt Bumper	\$ R	880.00 ✓
6	1 pc	Frt Bumper Bracket LH	\$ R	79.00 X
7	1 pc	Frt Wing Mirror LH	\$ R	98.00 ✓
8	1 pc	Frt View Mirror (Round)	\$ R	75.00 X
9	1 pc	Frt Mirror Support LH	\$ R	324.00 ✓
10	1 pc	Step Garnish LH	\$ R	235.00 ✓
				\$ 3,180.00
Less 10%				\$ 318.00
				\$ 2,862.00
11	1 pc	Frt Door Co's Sticker LH	\$	25.00
S/Nett				\$ 2,887.00
Parts Total :				\$ 2,887.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$	80.00 20l
2		To remove, repair & replace damaged bodyparts and where consistent to the accident.	\$	400.00 30d
3		Putty and respray painting on affected portions.	\$	500.00 40d
Labour Total :				\$ 980.00
Total Parts & Labour				\$ 3,867.00

for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: