

Submit to insurance

not allowed later

19/8/21 45810,700

10 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: GBJ 4492K

NETT ITEM

1PC	REAR WINDSCREEN	shattered	1455.00	\$1,455.30 ✓
1PC	REAR WINDSCREEN MOULDING	rs		\$110.10 X
1PC	TAILGATE	Body ID	1978.40	\$2,245.10 ✓
1PC	TAILGATE REAR LOGO	new		\$68.60 ✓
1PC	TAILGATE ' NV 200 ' EMBLEM	new	79.90	\$118.00 ✓
1PC	TAILGATE ' VANETTE ' EMBLEM	new	80.00	\$105.00 ✓
1PC	TAILGATE ' 600kg ' STICKER	new	60.00	\$80.00 ✓
1PC	TAILGATE INNER TRIM	Dis	315.40	\$525.20 ✓
1SET	TAILGATE INNER TRIM CLIPS	new	35.00	\$45.00 ✓
1PC	TAILGATE INNER LOCK	DD/SM	145.50	\$399.20 ✓
1PC	TAILGATE INNER LOCK GARNISH	see		\$105.10 X
1PC	TAILGATE OUTER HANDLE GARNISH	Surf/one	241.20	\$428.90 ✓
1PC	TAILGATE WEATHERSTRIP	YWI	282.50	\$335.80 ✓
1PC	TAILGATE INNER CLOSING HANDLE	11		\$60.00 X
2PCS	TAILGATE DAMPERS @\$288.00	11		\$576.00 X
1PC	TAILGATE REAR WIPER ARM	Surf		\$145.80 ✓
1PC	TAILGATE REAR WIPER BLADE	Surf	82.50	\$100.60 ✓
1PC	TAILGATE REAR WIPER MOTOR	JM	455.30	\$625.60 ✓
1PC	REAR BUMPER	DD	612.20	\$745.60 ✓
1PC	REAR BUMPER SPONGE	Torn	122.50	\$244.50 ✓
2PCS	REAR BUMPER SIDE HOLDERS @\$65.00	Surf	45 x 2 = 90	\$130.00 ✓
1SET	REAR BUMPER CLIPS	new	35.00	\$39.00 ✓
1PC	REAR END PANEL OUTER	Body ID	255.20	\$899.20 ✓
1PC	REAR END PANEL INNER	Body ID	485.30	\$845.90 ✓
1PC	REAR END PANEL TOP GARNISH	YWI	83.30	\$285.00 ✓
1PC	REAR FLOOR PANEL	crumpled/see	1420.30	\$1,999.50 ✓
1PC	REAR FLOOR PANEL TOP CARPET	Torn	580.00	\$820.00 ✓
2PCS	TAILLAMPS @\$655.00	one	304.50 x 2 = 609.00	\$1,310.00 ✓
2PCS	TAILLAMP HOUSING PANELS @\$685.00	R		\$1,370.00 X
1PC	REAR EXHAUST	11		\$682.30 X
1PC	RESR EXHAUST MOUNTING	11		\$50.00 X
1PC	REAR SPARE TYRE BRACKET	11		\$369.20 X
2PCS	REAR FENDERS @\$1499.30	R		\$2,998.60 X
1PC	REAR FENDER OUTER RAILING END O/S	one	45.00	\$65.00 ✓
				\$20,383.10

S.NETT

1SET	TAILGATE 70km/h & 6 PAX STICKER	new		\$20.00 ✓
1PC	REAR WINDSCREEN SEALANT	new		\$40.00 ✓
1PC	REAR WINDSCREEN INNER SEAL	new		\$30.00 ✓

1PC	REAR WINDSCREEN SOLAR FILM	<i>nee</i>	\$200.00	<i>150</i>
1SET	REAR REVERSE SENSOR	<i>shook</i>	\$250.00	<i>200</i>
1SET	REAR REVERSE CAMERA	<i>shook</i>	\$380.00	<i>280</i>
1PC	REAR LICENCE PLATE	<i>sig</i>	\$50.00	<i>x</i>
1SET	REAR VIDEO CAM ASSY	<i>dayo/m.s</i>	\$650.00	<i>380</i>
1PC	REAR FLOOR PANEL TOP WOODEN	<i>one</i>	\$900.00	<i>500</i>
1PC	REAR END PANEL SEALANT	<i>nee</i>	\$50.00	<i>✓</i>

TO CHECK WIRING	\$50.00	<i>30</i>
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	<i>50</i>
TO DISMANTLE & BREPLACED REAR WINDSCREEN	\$150.00	<i>100</i>
TO DISMANTLE & REFIX GARNISH UPHOLSTERY	<i>m</i> \$120.00	<i>x</i>
TO TRANSFER TAILGATE MECHANISM	\$100.00	<i>60</i>
TO DISMANTLE & REFIX REAR EXHAUST	<i>11</i> \$100.00	<i>x</i>
TO MOUNT VEHICLE ON CAR O-LINER	<i>11</i> \$380.00	<i>x</i>
TO SPRAY RUST PROOFING	\$150.00	<i>100</i>
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,500.00	<i>1500</i>
TO PUTTY & SPRAY PAINTING	\$1,800.00	<i>1100</i>
<b>TOTAL</b>	<b>\$28,383.10</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*p- 9764*  
*102*  
*p- 878760*  
*S.N- 1650*  
*L- 2940*  


---

*13377.6*  


---

*21 1/2*  


---

*10707.*