



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008732/Uuf3n2	
			Date: 25/08/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 147E	Veh. Inspected	SNA 8398D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/21/2046	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	19/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SERENA HIGHWAY STAR (A)	c.c	1198
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JN1EBAC27Z0001067	Colour	PEARL WHITE
	Odometer	738 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	BRIDGESTONE	9 mm
	L/H Front Tyre	195/60 R16	BRIDGESTONE	9 mm
	R/H Rear Tyre	195/60 R16	BRIDGESTONE	9 mm
	L/H Rear Tyre	195/60 R16	BRIDGESTONE	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/08/2021	Inspection Date	19/08/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	