

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD	Ref:	CS/SMR21008738/Ttf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705	Date:	16/04/2022	
			Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5819S	Veh. Inspected	SKW 7093J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/08/21/2039	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	19/08/2021	
2.	. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	RU11103258	Colour	WHITE	
	Odometer	136016 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/08/2021	Inspection Date	20/08/2021	
	Survey held at	RICO 60 AUTO SERVICES PTE	LTD		
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	6 Worl	king Days	