



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0660/2021/KS 21-Sep-21 CHANG 1 of 1 SMQ 8218 T AUDI Q3 SPORTBACK 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO RESPRAY BOTH LHS DOOR COVERS <i>HL</i>	\$ 800.00	<i>400</i>
GRAND TOTAL		\$ 800.00	

For Premium Automobiles Pte Ltd

Adrian Ling -
22/09/21.
HL



Authorised Signature

Car-in

20/9/21

wip: 397-20.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam/



AIG - Adrian

- 5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER SPOILER <i>2nd</i>	1	\$ 459.00	✓
2	REAR WHEEL ARCH COVER LH / RH <i>LH out, RH new</i>	2	\$ 1,072.00	✓
2	REAR DOOR LH <i>Dented</i>	1	\$ 2,816.00	✓
3	REAR DOOR OUTER SEAL LH <i>new</i>	1	\$ 135.00	✓
4	REAR DOOR CATCH LH <i>Damaged</i>	1	\$ 120.00	✓
5	REAR DOOR COVER LH <i>out</i>	1	\$ 349.00	✓
6	<i>T.S</i>	1	\$ 2,816.00	X
7	FRONT DOOR OUTER SEAL LH <i>new</i>	1	\$ 166.00	X
8	FRONT DOOR CATCH LH <i>new</i>	1	\$ 120.00	X
9	FRONT DOOR COVER LH <i>out</i>	1	\$ 370.00	✓
10	FRONT WHEEL ARCH COVER LH <i>out</i>	1	\$ 536.00	✓
11	FRONT ALUMINIUM RIM LH <i>out</i>	1	\$ 1,262.00	✓
12	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 10,521.00	
TOTAL LABOUR CHARGES		:	\$ 9,532.00	
GRAND TOTAL		:	\$ 20,053.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Supp labour

1) To respray both LHS Door covers.

400