

366013
274509

TOTAL PRICE \$ 14,783.92
LESS: 25% \$ 3,695.98
SUB TOTAL PRICE \$ 11,087.94

CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER SIDE GARNISH CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
2	FRONT BUMPER STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 500.00	\$ 500.00 <i>+200</i>
3	HEADLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
4	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
5	FRONT CORNER PANEL RH STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 400.00	\$ 400.00 <i>80</i>
6	FRONT STEP PANEL GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
7	FRONT DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
8	FRONT DOOR RH STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 1,000.00	\$ 1,000.00 <i>300</i>
9	FRONT DOOR ARCED GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
10	FRONT DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>

600 TOTAL \$ 2,360.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,200.00	<i>400</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	<i>500</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>40</i>
4	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	<i>x</i>
6	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>x</i>
7	TRANFER FRONT DOOR MECHANISM	\$ 120.00	<i>x</i>
8	REMOVE AND REINSTALL WINDOW GLASS	\$ 60.00	<i>x</i>
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$ 3,320.00

TOTAL PARTS COST : \$ 13,447.94
TOTAL LABOUR COST : \$ 3,320.00
TOTAL REPAIR COST : \$ 16,767.94

Adrian Gij
W/S. 04/10/21
04 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,
IRENE
SERVICE ADVISOR
IRENE
HP : 9151 6861

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 4285.09
W/S: 3.41c