

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717  
 Tel No. : 67433246 / 67438552 Fax No. : 67430013  
 E-Mail : peoplevehicle@gmail.com  
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

KDY2318022528

**AXA INSURANCE PTE LTD**  
 8 Shenton Way #27-01  
 AXA Tower (S) 068807

Attention : Motor Claim Department  
 Contact : 63387268 Fax No. : 68804838

*Cecilia*

**Estimate : ES21013**

Date : 18/08/2021  
 Vehicle Num. : GBE 6820 K  
 Make/Model : TOYOTA DYNA KDY231  
 Chassis/Eng# :  
 Accident Date : 17/08/2021  
 Claim No. : TT 402-21  
 Reference : YQ 3730 X  
 Policy No. : NTUC5115028562-01

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAILGATE PANEL <i>Dented</i>		<del>1,950.00</del> <i>1588.</i>
2.	2	TAIL LAMP <i>HTCracked</i>	228.40	<del>456.80</del> <i>228.40</i>
3.	1	TAIL LAMP BASE PANEL L/H REAR <i>Bent.</i>		78.00 ✓
4.	1	REFLECTOR L/H REAR <i>crack</i>		45.00 ✓
5.	1	WINDSCREEN RUBBER FRT <i>new</i>		378.29 ✓
6.	1	PANEL FRT <i>Dented</i>		987.00 ✓
7.	1	PANEL TOP GARNISH FRT <i>cut</i>		378.20 ✓
8.	1	GRILLE <i>cracked</i>		434.80 ✓
9.	1	GRILLE LOGO <i>new</i>		121.30 ✓
10.	2	HEAD LAMP <i>cracked</i>	675.40	1,350.80 ✓
11.	1	BUMPER FRT <i>Behind</i>		378.30 ✓
12.	2	BUMPER BRACKET FRT <i>Bent.</i>	278.20	556.40 ✓
13.	2	BUMPER FOG LAMP FRT <i>new</i>	278.20	556.40 ✓
14.	1	SIDE MIRROR ARM L/H <i>new</i>		356.10 ✓

*6525.49.*  
*4894.11*

List Total S\$ : 8,027.39  
 25.00% Discount S\$ : 2,006.85  
**6,020.54**

SPECIAL NETT ITEMS :				
1.	1	ALUMINIUM HOOD GLASS <i>cracked</i>		220.00 ✓
2.	1	ALUMINIUM HOOD GLASS RUBBER <i>new</i>		85.00 ✓
3.	1	NUMBER PLATE FRT <i>Bent</i>		30.00 ✓
4.	1	NUMBER PLATE REAR <i>Bent</i>		30.00 ✓
5.	1	70 KM/H STICKER ?		15.00 ✓
6.	1	13 PAX STICKER <i>new</i>		15.00 ✓

CONTINUE / ...

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717  
 Tel No. : 67433246 / 67438552 Fax No. : 67430013  
 E-Mail : peoplevehicle@gmail.com  
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

AXA INSURANCE PTE LTD  
 8 Shenton Way #27-01  
 AXA Tower (S) 068807

Attention : Motor Claim Department  
 Contact : 63387268 Fax No. : 68804838

Estimate : ES21013

Date : 18/08/2021  
 Vehicle Num. : GBE 6820 K  
 Make/Model : TOYOTA DYNA KDY231  
 Chassis/Eng# :  
 Accident Date : 17/08/2021  
 Claim No. : TT 402-21  
 Reference : YQ 3730 X  
 Policy No. : NTUC5115028562-01

S/N	Quantity	Particular	Unit Price	Amount S\$
7.	2	GREEN & WHITE STICKER <i>New</i>	15.00	30.00 ✓
		<i>425</i>		
		Special Nett Total S\$ :		425.00
		LABOUR :		
		REMOVE & REPLACE ACCIDENT DAMAGED PARTS		<del>1400.00</del> 1200 ✓
		SPRAY PAINTING ACCIDENT AFFECTED PARTS		800.00 ✓
		REMOVE AND REFIX FRT WINDSCREEN		100.00 ✓
		REMOVE & REFIX DASHBOARD & CHECK WIREING		<del>280.00</del> 60 ✓
		REMOVE AND REFIX AIR CON BOWLER & SUPPLY GAS		120.00 ✓
		REMOVE AND REPLACE ALUMINIUM HOOD GLASS		80.00 ✓
		UNDERCOAT		<del>120</del> 80 ✓
		Labour Total S\$ :	<i>2320</i>	2,780.00

SingDollars : Nine Thousand Two Hundred Twenty-Five & Cents Fifty-Four Only

E. & O.E.

Total S\$ : 9,225.54

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice.No Signature Required.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adrian G  
 H/S 19/08/21  
 10 Days.  
 total : 7639.11  
 H/S : 6.1K.*