

CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, Singapore 729667

Tel: +65 6966 0666

Email: claims@crownasia.com.sg

Company Reg No: 201023449R

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811

17 AUG 2021

Attn: Motor claims dept

Dear Sir/Madam,

THIRD PARTY CLAIM – REPAIR ESTIMATE FOR PZ 955 T

Traffic accident involving PZ955T and SLA1874R along VICTORIA STREET on 14/01/2019

Vehicle owner

: RUI FENG CHARTERED PTE LTD

Vehicle No.

: PZ955T

Model

: TOYOTA HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB

Date of Damaged

: 14/01/2019

We append below the estimate repair cost for PZ955T: -

Part required:-

1 pc

Front left side mirror

\$ 350.00

Less 10% trade discount

\$ 35.00 \$ 315.00

Labour charges:-

To knock and all necessary part including changing of all damaged part.

To putty and spray and painting on Front bumper, Front bonnet,

Front left door panel, Front left side mirror panel.

\$ 1200.00

\$ 1515.00

Please arrange for your surveyor to survey the vehicle at 44 Sungei Kadut Ave, S729667. Kindly contact Mr Andy, 8331 5664 to arrange for the surveyor.

Yours faithfully

