



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21008798/T1ra3q2 Date: 09/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9244L	Veh. Inspected	JTY 2878
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03FYV	Excess (\$)	0.00
	Assign From		Assign Date	23/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA Y15ZR	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	PMYUG0520L0107357	Colour	GREEN
	Odometer	29572 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90 R17	PIRELLI	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70 R17	PIRELLI	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/08/2021	Inspection Date	23/08/2021
	Survey held at	KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	