

REF: CC3/AIG21008799/Aqc

ASS. REG. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **3268738536SG**

Sum Insured: _____ Excess: **0/-**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **131K(est)**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **15** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMA4427S** Yr Regn: **2018 / June**

Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Audi A5 SB.** c.c. **1984**

Colour: **Blue** A/C: **Insured / Std / NI / NA**

Sp. Reading: **63200** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **WAUZZZF54JA099662**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **245/40R18-**

R: **245/40R18-**

BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. **06** mm R/Bal. **06** mm

L/Bal. **06** mm L/Bal. **06** mm

D.O.A. _____ D.O.I. **20/08/21**

Survey held at **Premium**

Des. of Damages: **Frt** / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG

24/08/21@8.24am revert to AIG via Merimen.

24/08/21@12.39pm Kok Chong informed C/A via Merimen.

MV: 24/08/21@3.01pm Informed Kee Siang C/A & ex:\$0/- by email.

PV: **60K** 30/08/21@10.02am 2nd revert to AIG via Merimen. (supplementary)

Nett: 30/08/21@12.32pm Kok Chong informed can proceed supplementary.

30/08/21@3.54pm Informed Kee Siang proceed supplementary by email.

13/10/21@4.18pm confirmed with Mr Boo final fig \$41587.04, 15 days. (Red \$54583.96, 57%)

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: **15**

1)

: Final Report

Resurvey No. of Trip: **2**

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

Report Format: **MER-OD**

Final Fee / B.I: \$ **41587.04**

: Weekend (\$)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/08/2021 10:33 (SGT)
Date of Accident 18/08/2021 06:45 (SGT)
Exact Location of Accident Near 1 Lor Chuan, Singapore 556818
Additional Location Information ALONG CTE AFTER ANG MO KIO AVE 1 TOWARDS CITY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMA4427S

INSURED/POLICYHOLDER

Is company? No
Name of Registered Owner LIM THOU YEE
NRIC No SXXXX271Z
Email Address THOUYEE@HOTMAIL.COM
Mobile Phone No (Phone) +65-98787325
Alternative Phone No +65-98787325

VEHICLE PARTICULARS

Manufacturer Audi
Model A5
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1984

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1800052485-03
Cover Note Number -

DRIVER

Name of Driver ZHOU HOU MENG
NRIC No SXXXX166B

Date Of Birth	01/06/1980
Occupation	Indoor
Date Of Driving Pass	24/02/1999
Driving experience	22 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96636121
Alt. Phone Number	-
Email Address	TAOMIN80@GMAIL.COM
Address	10 FLORA DRIVE #04-08 FERRARIA PARK
Address complement	-
Postcode	506942
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG CTE TOWARDS CITY FOR WORK. THE ROADS WERE WET WITH A SLIGHT DRIZZLE. THE VEHICLE IN FRONT (SFP 8233 L) SLOWED DOWN AND COME TO A STOP. I ASLO SLOWED DOWN AND CAME TO A STOP. SUDDENLY MY VEHICLE (SMA 4427 S) WAS HIT IN THE BACK BY SLM 8543 E TWICE. THE IMPACT WAS SO HUGE THAT IT MADE MY CAR RICOCHET TO THE FRONT AND HIT SFP 8223 L

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFP8233L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM9543E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHONG HOU MENG
Gender	Female
Phone No	(Phone) +65-96636121
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMA4427S
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 15/22/21
18/04/2021
Policyholder's Signature / Date & Time

 15/22/21
18/04/2021
Driver's Signature (If driver is not the policyholder) / Date & Time

 
Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

I WAS DRIVING ALONG CTE TOWARDS CITY FOR WORK. THE ROADS WERE
WET WITH A SLIGHT DRIZZLE. THE VEHICLE IN FRONT (SFP 8233L) SLOWED DOWN
AND CAME TO A STOP. I ALSO SLOWED DOWN AND CAME TO A STOP.
SUDDENLY MY VEHICLE (SMA 4427S) WAS HIT IN THE BACK BY SLM 9543E
TWICE. THE IMPACT WAS SO HUGE THAT IT MADE MY CAR RICOCHET TO THE
FRONT AND HIT SFP 8233L.

Declaration

We declare the foregoing particulars are true in every respect.

 1574HR
18 AUG 2021
Policyholder's Signature / Date & Time

 1520HR
18 AUG 2021
Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0671/2021/JT
DATE : 19-Aug-21
WIP : 40321

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY 19/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM THOU YEE
ADDRESS : 10 FLORA DRIVE #04-08
FERRARIA DRIVE
SINGAPORE 506942
TELEPHONE : HP +65 98787325
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800052485-03
VEHICLE NO : SMA ~~4472~~⁴⁴²¹-S
MODEL CODE : A5 SB 2.0 TFSI
MODEL YEAR : 7/6/2018
ENGINE NO : CVK 061652
CHASSIS NO : WAUZZZF54JA099662
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-21
PLACE OF ACCIDENT : ALONG CTE AFTER ANG MO KIO
AVE 1 TOWARDS CITY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4472 S - FRONTAL

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	500
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COLLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00	✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS.	S/N \$	560.00	✓
5	TO RENEW ENGINE MAGNET AND OTHER ENGINE COMPONENTS.	S/N \$	480.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	6,400.00	1500 (Without lock carrier) 2750 (With lock carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$	6,000.00	3300
TOTAL LABOUR CHARGES - FRONT		:	\$ 16,420.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4472 S - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	X
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	X
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$	480.00	X
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED ✓	\$	4,800.00	750
8	TO RESPRAY REAR BUMPER, REAR END PANELLING, SPARE WHEEL HOUSING, REAR LID AND HINGES ✓	\$	4,000.00	1100.
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$	280.00	X
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES - REAR		:	\$ 11,664.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	1	\$ 2,251.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 407.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	1	\$ 72.00	+
4	FRONT BUMPER GRILLE CENTER <i>new</i>	1	\$ 196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 228.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH ?	2	\$ 126.00	?
7	RADIATOR GRILLE <i>crushed.</i>	1	\$ 2,326.00	✓
8	RADIATOR GRILLE SENSOR SUPPORT - LH / RH <i>Repd</i>	2	\$ 102.00	✓
9	RADIATOR GRILLE COVER - UPPER <i>crushed.</i>	1	\$ 189.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 948.00	+
11	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1	\$ 124.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 845.00	?
13	FRONT BUMPER BRACKET LH / RH ?	2	\$ 428.00	?
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 72.00	+
15	FRONT BUMPER TOP COVER <i>Distorted</i>	1	\$ 127.00	✓
16	"CAUTION" STICKER ?	1	\$ 14.00	✓
17	"A/C" STICKER <i>new</i>	1	\$ 8.00	✓
18	FRONT LOCK CARRIER UPPER BRACKET ?	1	\$ 137.00	?
19	FRONT LOCK CARRIER LOWER BRACKET - LH / RH ?	2	\$ 58.00	?
20	HORN LH / RH ?	2	\$ 252.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,910.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH / RH ?	2	\$ 58.00	?
22	FRONT PARKING AID SENSOR - INNER ?	2	TBC	?
23	FRONT PARKING AID SENSOR SEAL RING - INNER?	1	\$ 510.00	?
24	FRONT FENDER - LH / RH LH Repair, RH Buckled	2	\$ 2,120.00	1060
25	FRONT FENDER ATTACHMENT PARTS - LH / RH	2	\$ 53.00	+
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 148.00	+
27	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00	+
28	FRONT FENDER BRACE - LH / RH	2	\$ 236.00	+
29	FRONT FENDER CHROME TRIM - LH / RH new	2	\$ 328.00	✓
30	FRONT FENDER LONG FLEDGE COVER - LH / RH ?	2	\$ 72.00	?
31	FRONT FENDER SHORT FLEDGE COVER - LH / RH ?	2	\$ 32.00	?
32	FRONT WHEEL HOUSING LINER - LH / RH new	2	\$ 550.00	+
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS new	1	\$ 169.00	+
34	FRONT WHEEL SPOILER - LH / RH new	1	\$ 146.00	+
35	BONNET Distorted	1	\$ 3,312.00	✓
36	BONNET ATTACHMENT PARTS new	1	\$ 123.00	+
37	BONNET HINGE - LH / RH new	2	\$ 838.00	+
38	BONNET IMPACT PROTECTION - CENTER ?	1	\$ 28.00	✓
39	BONNET IMPACT PROTECTION - LH / RH new	2	\$ 56.00	✓
40	BONNET SOUND ABSORBER new	1	\$ 343.00	+
SUBTOTAL SPARE PARTS			\$ 9,192.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - LH / RH ?	2	\$ 100.00	?
42	BONNET LOCK - LH / RH ?	2	\$ 427.00	?
43	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
44	BONNET BOWDEN CABLE COVER - CENTER } new	1	\$ 10.00	X
45	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
46	BONNET RELEASE LEVER } new	1	\$ 14.00	X
47	BONNET LOCK CABLE } new	1	\$ 74.00	+
48	PLENUM CHAMBER COVER - CENTER new	1	\$ 97.00	+
49	PLENUM CHAMBER COVER - LH / RH new	2	\$ 144.00	+
50	LED HEADLIGHT - LH / RH included	2	\$ 15,804.00	✓
51	LED HEADLIGHT POWER MODULE - LH } new	1	\$ 758.00	+
52	LED HEADLIGHT CONTROL UNIT - LH } new	1	\$ 751.00	+
53	LED HEAT SINK - LH new	1	\$ 1,153.00	+
54	LED HEADLIGHT HOSE - LH new	1	\$ 36.00	+
55	LIFT CYLINDER - LH / RH } new	2	\$ 396.00	+
56	LIFT CYLINDER HOSE } new	1	\$ 86.00	+
57	LOCK CARRIER included	1	\$ 1,016.00	✓
58	LOCK CARRIER RADIATOR LOWER SUPPORT LH / RH new	2	\$ 152.00	+
59	A/C' CONDENSOR Dented	1	\$ 622.00	✓
60	A/C' PRESSURE SENDER ?	1	\$ 186.00	?
SUB TOTAL SPARE PARTS			\$ 21,942.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

photo.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	"A/C" REFRIGERENT LINE ?	1	\$	167.00	+
62	"A/C" REFRIGERENT LINE	1	\$	340.00	+
63	"A/C" REFRIGERENT LINE	1	\$	248.00	+
64	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$	19.00	?
65	CHARGE AIR COOLER	1	\$	587.00	+
66	CHARGE AIR COOLER PRESSURE HOSE ?	1	\$	357.00	+
67	CHARGE AIR COOLER PRESSURE PIPE ?	1	\$	427.00	+
68	RADIATOR ?	1	\$	904.00	?
69	RADIATOR UPPER SECURING PIN ?	2	\$	5.00	?
70	RADIATOR LOWER SUPPOER RUBBER BUSH ?	2	\$	25.00	?
71	RADIATOR COOLANT ?	6	\$	142.00	?
72	RADIATOR FAN RING	1	\$	267.00	+
73	RADIATOR FAN WITH CONTROL UNIT	1	\$	2,318.00	+
74	RADIATOR AIR DUCT - LH / RH ?	2	\$	64.00	?
75	RADIATOR AIR DUCT - LH / RH ?	2	\$	32.00	?
76	RADIATOR AIR DUCT - UPPER ?	1	\$	16.00	?
77	RADIATOR AIR DUCT - LOWER ?	1	\$	22.00	?
78	ENGINE AIR FILTER	1	\$	386.00	+
79	AIR INTAKE DUCT	1	\$	22.00	+
80	AIR INTAKE GUIDE - RH	1	\$	53.00	+
SUB TOTAL SPARE PARTS			\$	6,401.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	AIR INTAKE AIR FLOW SENSOR	1	\$ 567.00	f
82	AIR INTAKE HOSE	1	\$ 95.00	f
83	AIR INTAKE HOSE COVER	1	\$ 240.00	x
84	ENGINE CAM MAGNET	1	\$ 169.00	x
85	TUBE FOR OIL DIPSTICK	1	\$ 110.00	x
86	COOLANT TOP HOSE WITH QUICK RELEASE COUPLING	1	\$ 71.00	f
87	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 31.00	f
88	COOLANT PIPE	1	\$ 54.00	f
89	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 183.00	f
90	FRONT DOOR CHROME TRIM - LH / RH	2	\$ 328.00	✓
91	FRONT WINDOW CHROME SLOT SEAL - LH / RH	2	\$ 798.00	f
92	REAR BUMPER	1	\$ 2,504.00	✓
93	REAR BUMPER FIXING PARTS	1	\$ 165.00	x
94	REAR BUMPER SECURING STRIP	1	\$ 223.00	?
95	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	✓
96	REAR BUMPER LIGHT REFLECTOR - LH / RH	2	\$ 82.00	x
97	LED TAILLIGHT - LH / RH	2	\$ 2,038.00	f
98	LED TAILLIGHT TRIM - LH / RH	2	\$ 60.00	f
99	LED LISENCE PLATE LIGHT - LH / RH	2	\$ 202.00	f
100	REAR BUMPER REINFORCEMENT BEAM	1	\$ 940.00	?
SUB TOTAL SPARE PARTS			\$ 9,876.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
101	REAR BUMPER SEAL ?	2	\$ 28.00	?		
102	REAR BUMPER GUIDE SECTION - LH / RH <i>Men.</i>	2	\$ 46.00	X		
103	REAR PARKING AID SENSOR - LH / RH ?	2	TBC	?		
104	REAR PARKING AID SENSOR SEAL RING ?	2	\$ 14.00	?		
105	REAR LID <i>Rejis</i>	1	\$ 3,818.00	X		
106	REAR LID HINGE LH / RH	2	\$ 458.00	X		
107	REAR LID ATTACHMENT PARTS <i>Men</i>	1	\$ 153.00	X		
108	REAR LID LOCK WITH MICRO SWITCH	1	\$ 248.00	X		
109	REAR LID LOCK COVER <i>Men</i>	1	\$ 13.00	X		
110	REAR LID GASKET	1	\$ 236.00	X		
111	REAR LID PUSH BUTTON <i>Men</i>	1	\$ 1,389.00	X		
112	REAR LID STRIKER PLATE	1	\$ 66.00	X		
113	REAR LID PACKING ADHESIVE <i>Men</i>	1	\$ 19.00	✓		
114	"AUDI" EMBLEM <i>Men</i>	1	\$ 156.00	✓		
115	"A5" EMBLEM <i>Men</i>	1	\$ 99.00	✓		
116	"TFSI" EMBLEM <i>Men</i>	1	\$ 99.00	✓		
117	REAR WINDSCREEN <i>Men</i>	1	\$ 1,168.00	X		
118	REAR WINDSCREEN PRIMER <i>Men</i>	1	\$ 20.00	X		
119	ADDIATIONAL BRAKE LIGHT <i>Men</i>	1	\$ 576.00	X		
120	REAR CROSS PANEL <i>Rejis</i>	1	\$ 356.00	X		
SUB TOTAL SPARE PARTS			: \$ 8,962.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
121	REAR CROSS PANEL REINFORCEMENT <i>Ryis</i>	1	\$	632.00	<i>x</i>
122	REAR CROSS PANEL TRIM <i>new</i>	1	\$	360.00	<i>x</i>
123	FRONT NO PLATE <i>Painted</i>	S/N	\$	60.00	<i>—</i>
124	FRONT NO PLATE <i>Painted</i>	S/N	\$	60.00	<i>—</i>
125	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	<i>x</i>
126	ARCYLIX SEALANT	S/N	\$	180.00	<i>x</i>
127	CAVITY WAX	S/N	\$	140.00	<i>x</i>
128	STONE CHIP	S/N	\$	180.00	<i>x</i>
129	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00	<i>x</i>
130	SUNDRIES <i>?</i>		\$	400.00	<i>?</i>
TOTAL SPARE PARTS (FRONT + REAR)			:	\$ 67,775.00	
TOTAL LABOUR CHARGES (FRONT + REAR)			:	\$ 28,084.00	
GRAND TOTAL			:	\$ 95,859.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
 SURVEYED DATE : *20/08/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 12 Days (Without Lock Carrier) 15 Days (With Lock Carrier)*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type :	Singapore NRIC
Owner ID:	271Z
Vehicle Details	
Vehicle No.:	SMA44275
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2021
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CVK061652
Chassis No.:	WAUZZZF54JA099662
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$37,959.00
Original Registration Date:	07 Jun 2018
First Registration Date:	07 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$45,143.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2028
PARF Rebate Amount:	\$33,857.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,600.00
COE Rebate Amount:	\$26,145.00
Total Rebate Amount:	\$60,002.00

The information contained herein is correct as at 22 Aug 2021

OK