

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 24 Aug 2021

Preliminary Advice

Vehicle No	: SMX4671G	Accident Date	: 18/08/2021
Make	: AUDI Q3 SPORTBACK	Policy No.	: 7210003361
Assignment Date	: 20/08/2021	Excess	: S\$800.00
Date of Inspection	: 20/08/2021	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,200.00
Revised Amount	:S\$	5,304.00
Check Items (Estimated)	:S\$	370.00
Total	:S\$	5,674.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	71,550.00
Salvage Value	:S\$	
Margin for Repair	:S\$	88,450.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Due to SG car mart is down, the market value quoted is indicative. Will re-provide a market value (if need) once SG car mart is available.
Please take note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.