

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

20-Aug-21

Our ref : TP/5018/21

Joyous SE Engineering

TP Chim.

Xiao Tong

Chuan Teiping

RE : estimate cost for vehicle no : GBJ 3308S

1 pc	frt bumper	Delhd	\$	671.90	nett	✓
1 pc	frt lh door	Repr		1,071.40	x	
1 pc	lh railing door	Dented		1,352.40	✓	
1 pc	frt lh step garnish	Repr		78.00	x	
1 pc	lh headlamp	at		481.50	✓	
1 pc	rear lh fender	Repr		2,508.60	x	
1 pc	rear lh hup cap	could		161.30	✓	
				6,325.10		
			less 10%	632.51		
				5,692.59		
						2667.10
						2400.39
1 pc	frt lh door Co logo	new		300.00	nett	180
1 pc	frt lh door body sticker	new		35.00	✓	
1 pc	lh railing door logo	new		400.00	300	
1 pc	rear lh fender logo			400.00	300	
1 pc	lh railing door gum			50.00	x	
	Panel beating.			1,000.00	600	
	Spray painting.			1,000.00	800	
	Wiring.			30.00	✓	
	Remove & refit lh railing door glass.			100.00	40	
	Transfer door parts.			100.00	40	
				9,107.59		
			Plus 7% GST	637.53		
				9,745.12		
						815
						1510

SD : Nine thousand seven hundred forty-five & cents twelve only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian Lj
2/5 21/08/21

06 Days

total: 4725.39
L/s: 3.7K