




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS3/ASM21008841/Evce2 Date: 31/08/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 2091T	Veh. Inspected	XE 3169S
	Policy No.	GA577177	Coverage (\$)	0.00
	Claim No.	S1M03G28	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	23/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FUSO FV51	c.c	11967
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	FV51SJA20241	Colour	WHITE
	Odometer	327788 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	315/80 R22.5	EFFIPLUS	4 mm
	L/H Front Tyre	315/80 R22.5	EFFIPLUS	4 mm
	R/H Rear Tyre	315/80 R22.5	EFFIPLUS	4 mm
	L/H Rear Tyre	315/80 R22.5	EFFIPLUS	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
5. General Information				
	Accident Date	19/08/2021	Inspect Date / Time	24/08/2021 (01:09 PM)
	Survey held at	24 Tuas Avenue 2 Singapore 639455		
	Repairer	KOH KOCK LEONG ENTERPRISE PL		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$30,000-\$35,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	

Report Ref No. CS3/ASM21008841/Evce2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.