



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To perform anti-rust treatment on affected areas	60.00	30
4	Check and wheel computerize alignment	80.00	60
5	To remove and refix front tyre and wheel balancing in order to rear rim LH	50.00	30
	1020		
	Labour Total :	1790.00	
	TOTAL (PARTS & LABOUR):	3946.00	

P- 1196
M- 700
L- 1020
Supp- 906
3822

L/S- 3057.60
= 3050

Steve (LKK)
24/8/21, 11:30am

WHL RL
L/S
My RL Sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLM9598Y HYUNDAI TL TUCSON 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear door RH / <i>DD</i>		1210.00 /	
1	Rear door protector film RH / <i>1pc</i>		45.00 /	
1	Rear door lower garnish RH / <i>MIS</i>		145.00 /	
1	Rear fender lower garnish RH / <i>CUT</i>		95.00 /	
1	Rear fender RH (Repair refer to labour) <i>X R</i>		0.00	
1	Rear bumper (Repair refer to labour) <i>X 11</i>		0.00	
1	Rear rim 17 inch (Repair refer to labour) <i>X R</i>		0.00	
		Part Items Total:	1495.00	1495
			-20% -299.00	-299
			1196.00	1196
	<u>SPECIAL NETT ITEMS</u>			
1	Side skirt step up rails assy RH / <i>CUT</i>		680.00	500 /
1	Rear Tyre RH 225/60R17 / <i>TN (80% of \$250)</i>		280.00	200 /
		SN Items Total:	960.00	
		Total Parts	2156.00	700