

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 26 Aug 2021

Preliminary Advice

Insured Vehicle No	: SKT4688D	Accident Date	: 19/08/2021
TP Vehicle No	: SLF6456E	Assignment Date	: 26/08/2021
Make	: HONDA VEZEL	Est. Duration of Repair	: 8
Date of Inspection	: 24/08/2021		
Inspection At	: LION CITY RENTAL (JALAN LAM HUAT) (HQ) 60 JALAN LAM HUAT, 04-35/36 CARROS CENTRE SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,870.32
Revised Amount	:S\$	11,866.44
Check Items (Estimated)	:S\$	1,216.00
Total	:S\$	13,082.44

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost