

PC 3639H

<u>PARTS</u>				<u>S/N</u>		<u>LABOUR</u>		SUPP (PARTS)	
	\$671.10	\$0.00	\$0.00		\$0.00		\$20.00		\$0.00
	\$115.00	\$0.00	\$0.00		\$0.00		\$50.00		\$0.00
	\$700.00	\$0.00	\$0.00		\$0.00		\$30.00		\$0.00
	\$1,600.21	\$0.00	\$0.00		\$0.00		\$300.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$300.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		0%
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	SUPP (SN)	
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$700.00		\$0.00
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00					SUPP(LABOUR)	
	\$0.00	\$0.00	\$0.00					TOTAL	\$0.00
	\$0.00	\$0.00	\$0.00						\$2,314.73
	\$0.00	\$0.00	\$0.00						\$0.00
	\$0.00	\$0.00	\$0.00						\$700.00
	\$0.00	\$0.00	\$0.00						\$0.00
	\$0.00	\$0.00	\$0.00					SUPP	\$0.00
	\$0.00	\$0.00	\$0.00					<u>TOTAL SUPP</u>	\$0.00
	\$0.00	\$0.00	\$0.00					P/P	\$3,014.73
	\$0.00	\$0.00	\$0.00					MAKE / MODEL	TOYOTA HIACE (2982cc)
	\$0.00	\$0.00	\$0.00						\$3,014.73
	\$0.00	\$0.00	\$0.00					MARKET VALUE	\$35,000.00
	\$0.00	\$0.00	\$0.00					80%	LTA REBATE
	\$0.00	\$0.00	\$3,086.31						\$10,442.00
	\$0.00	\$0.00							\$24,558.00
	\$0.00	\$0.00							\$2,411.79
	\$0.00	\$0.00						L/S	\$2,400.00
	\$0.00	\$0.00						RED	\$2,936.00
	\$0.00	\$0.00						55%	
	\$0.00	\$0.00	\$3,086.31					TOTAL TP EST	\$5,336.00
	\$0.00	\$0.00	75%					REPAIR DAYS	2
	\$0.00		\$2,314.73					REMARKS	