

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : 20/21/21/VC05/024572 Date: 30th Sep 2021

Our Ref : CS/LPC21008882/Eqf3e2

M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE XE 3056J ACCIDENT ON 15/05/2021

Instruction was received to inspect the vehicle Reg. No. XE 3056J. The inspection was conducted on 24/08/2021 at the premises of M/s 10 Penjuru Close, Repairer: Kan Fook Sing Motor Workshop.

The following vehicle information was recorded:

Registration Number : XE 3056J Make/Model : Isuzu CYH52T

Year of Registration : 2017 Body Colour : White

Chassis Number : JALCYH52TH7000022

Engine Capacity : 15681 cc Speedometer Reading : Not Available

The vehicle sustained damages at the front. (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

(a) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES** (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989, that:

no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle. and we therefore recommend it to be written off as "Total Loss"

Market Value S\$ 259,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 28,178.00)

Nett Liability S\$ 230,822.00

Vehicle Inspected By:

CHEN TSUE YEE

CHEN TSUE YEE Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust),MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA), AM CATARI(CAN),M.MATA(USA),M.MdATA(USA), Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.