

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Misc. Insp (\$

Inspector's Signature:

Inspector's Stamp / License No.

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

7 Days.
before paint photos.
Gao Qianf
26/8/2021

TP/DS

liability
check

SG TP/DS - NEW scheme.

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Tau Wen Jun Andrew (Tu WenJun) 35B Nim Road Singapore 805071	
		Document No. 0	Mobile: 97606567	
		Document Date 23/08/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3800067075	2NRX522799	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:GBK7023G ACC DATE:22/08/2021 TP INS:CHINA TAIPING NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE				60.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				400.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40
6	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				180.00
7	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS AND WATER TEST.				396.00
8	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				360.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 1967000862

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Tau Wen Jun Andrew (Tu WenJun) 35B Nim Road Singapore 805071 Mobile: 97606567		
			Document No. 0				
			Document Date 23/08/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800067075		2NRX522799	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	B	BP-LAB2 R/I REAR CARPET, TRIMMING, REAR SEATS AND OTHER ATTACHMENT TO FACILITATE REPAIRS.					360.00 ✓
10	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				2160	4320.00
11	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				1770	3540.00
12	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION					183.18 ✓
13	1	T81551-52C90 LENS & BODY, RR X <i>nan</i>	1.00	369.40			369.40
14	2	T81561-52C90 LENS & BODY, RR <i>CRA</i>	1.00	369.40			369.40
15	3	T76817-26040 CLIP, BACK DOOR ?	2.00	3.60			7.20
16	4	T81581-52330 LENS & BODY, RR X <i>nan</i>	1.00	264.30			264.30
17	5	T81591-52330 LENS & BODY, RR X	1.00	264.30			264.30
18	6	SPC507-0D014 43 BACK SENSOR (218, ATTITUDE BLAC ?	1.00	172.40			172.40
19	7	S81910-0D020 REFLECTOR ASSY, REFL X	1.00	60.40			60.40
20	8	S81920-0D020 REFLECTOR ASSY, REFL X <i>nan</i>	1.00	60.40			60.40
21	9	T81480-52070 LAMP ASSY, RR FOG, X	1.00	236.70			236.70
22	0	T81481-52560 BRACKET, FOG LAMP X	1.00	56.50			56.50
23	1	T89997-30100 ANTENNA, ELECTRICAL ?	1.00	72.60			72.60
24	2	S52159-0U919 COVER, RR BUMPER, L <i>re.</i>	1.00	319.20			319.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Tau Wen Jun Andrew (Tu WenJun)				
		Document No. 0	35B Nim Road				
		Document Date 23/08/2021	Singapore 805071 Mobile: 97606567				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3800067075	2NRX522799	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
25	3	S52151-0D010 EXTENSION, RR BUMPER	1.00	191.80		191.80	
26	4	S52162-0D050 PLATE, RR BUMPER, NO	1.00	21.10		21.10	
27	5	S52161-0D070 EXTENSION, RR BUMPER	1.00	130.30		130.30	
28	6	S52162-0D040 EXTENSION, RR BUMPER	1.00	130.30		130.30	
29	7	S52161-0K040 CLIPS	10.00	4.10		41.00	
30	8	S52155-0D110 SUPPORT, RR BUMPER S	1.00	74.10		74.10	
31	9	S52156-0D100 SUPPORT, RR BUMPER S	1.00	74.10		74.10	
32	0	S52575-0D280 RETAINER, RR BUMPER	1.00	71.10		71.10	
33	1	S52576-0D270 RETAINER, RR BUMPER	1.00	71.10		71.10	
34	2	S58302-0D010 PANEL SUB-ASSY, LWR	1.00	702.90		702.90	
35	3	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	438.20		438.20	
36	4	S64716-0D170 CO COVER, DECK TRIM, RR	1.00	155.90		155.90	
37	5	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1041.50		1041.50	
38	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00	
39	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
40	8	S64813-0D330 DAM, BACK WINDOW GLA	2.00	12.50		25.00	
41	9	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1142.50		1142.50	
42	0	S67881-0D130 WEATHERSTRIP, BACK D	1.00	376.00		376.00	
43	1	S69350-0D240 LOCK ASSY, BACK DOOR	1.00	472.40		472.40	
44	2	S69430-0D090 STRIKER ASSY, BACK D	1.00	26.00		26.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others				
					Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9


17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1		Mr Tau Wen Jun Andrew (Tu WenJun)				
		Document No. 0		35B Nim Road				
		Document Date 23/08/2021		Singapore 805071 Mobile: 97606567				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP170R	MWYQKT E4	17/01/2020	SMR6730M	0	21200	69DS/SMR6730M	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3800067075		2NRX522799	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
45	3	T90975-02086 FRONT BONNET EMBLEM, 			1.00	72.20		72.20
46	4	S75442-0D290 PLATE, BACK DOOR NAM			1.00	35.80		35.80
47	5	S75441-0D070 PLATE, BACK DOOR NAM			1.00	53.70		53.70
48	6	S76801-0D600 GARNISH SUB-ASSY, BA			1.00	231.80		231.80
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
For & on behalf of		Acknowledged by Repairer		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Signature: 				18,379.18		
		Date: 						
		Please acknowledge receipt of vehicle						
				Parts		8,247.60	GST 7.00%	1,286.54
				Labour		9,548.40		
				Sublet		583.18	Less	0.00
				Lubrication/Fluid		0.00		
				Others		0.00		
						Amount Due		19,665.72

Customer Copy