



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: SALIHA SYED YUSOF		Ref: CS3/AIG20008852/R1tf3e2-1 Date: 07/09/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMM 1800D	Veh. Inspected	FBJ 2330H
Policy No.	1800156512	Coverage (\$)	0.00
Claim No.	4929508673SG	Excess (\$)	0.00
Assign From	SALIHA SYED YUSOF	Assign Date	24/08/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA CBR1000RR	c.c	999
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JH2SC59A9EK600429	Colour	MULTI COLOUR
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70ZR17	MITAS	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55ZR17	MITAS	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/08/2020	Inspection Date	24/08/2020
Survey held at	20 Bukit Batok Crescent, #01-19 Enterprise Centre		
Repairer	PRIMERO RACING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	