

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305484002
Date : 23 08 21
Time of Fax : _____

Via Fax : Email
Your Insured : SLC 8168P
Date of Acc : 23 08 21

Attn: Motor Claims Department

Aig Asia

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

C7764Y

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ <u>Lim Tien Siong</u>	<u>Tel: 6214 8398 or HP: 9635 8546</u>
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **limts@cdege.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: **23-Aug-21**

INSURANCE: **AIG ASIA**

MODEL: **Hyundai Ioniq**

MVA: **LIM T S**

VEHICLE NO.: **SHC7764Y- CityCab**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90
	Front Bumper Up Brkt RH	1		\$35.00
	Front Bumer Clips	10	\$2.20	\$22.00
	Front Fender RH	1		\$588.80
	Front Fender Blue-Drive RH	1		\$26.60
	Front Wheel Cap RH	1		\$346.40
	SUB TOTAL			\$1,449.70
	LESS 20%			\$289.94
	DISCOUNTED TOTAL			\$1,159.76
	Frt Westlake Tyre RH	1		\$216.00
	NETT TOTAL			\$216.00
	TOTAL SPARE PARTS			\$1,375.76
	<u>Labour Charge</u>			
	Panel Beating			\$400.00
	Spray Painting			\$600.00
	Tuff Kote			\$40.00
	Wheel Alignment			\$120.00
	TOTAL LABOUR			\$1,160.00
	ESTIMATE TOTAL			\$2,535.76
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SLC8168P

Date of Accident

23/08/2021



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**

Period of Insurance **01/04/2021 - 31/03/2022**

Requested By **Huang Xiao Yan (COMFORTDEL...**

Requested Date **23/08/2021 13:32**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**