

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMX5798T (Insd veh)	Model:	TOYOTA HIACE 3.0 D HIGH-ROOF 14 SEATER (A)
	SKJ7434C (TP veh)		
Date of Accident:	20/08/2021		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	<b>18,861.39</b>		
Final Repair Cost	: \$	4,400.00		
Loss of Use	: \$			6.00 days at \$80.00 per day
Rental (if any)	: \$			days
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (Global Sum)	: \$	4,400.00		

Is Third Party Workshop GIA Registered?		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For <b>Non GIA Registered Workshop:</b>	Agreed Liability	100		(%)
B) For <b>GIA Registered Workshop:</b>	BOLA Applicable: Yes/ No	BOLA Scenario No: _____		
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Xin Hua Workshop Pte Ltd	: \$	4,400.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

18 Apr  
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))