

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Monday, 11 October 2021 1:02 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: CTI-TP SMY 3746B SURVEYED BY KENNETH (OUR REF: CS/CTI21008919/Kqc)

Dear Shiau Chan,

Audit check done for SMY3746B, found fuel lid cover price too high.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Monday, 11 October, 2021 12:23 PM
To: Simon Ho (LKKAUTO)
Subject: RE: CTI-TP SMY 3746B SURVEYED BY KENNETH (OUR REF: CS/CTI21008919/Kqc)

Dear Simon,

For your re-audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Sent: Monday, 30 August 2021 11:01 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: CTI-TP SMY 3746B SURVEYED BY KENNETH (OUR REF: CS/CTI21008919/Kqc)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SMY3746B FOUND ESTIMATE WITHOUT PARTS PRICES, PARTS PRICES NEED VERIFICATION WHEN PROVIDED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)

Sent: Thursday, 26 August, 2021 3:25 PM

To: Simon Ho (LKKAuto)

Subject: CTI-TP SMY 3746B SURVEYED BY KENNETH (OUR REF: CS/CTI21008919/Kqc)

Dear Simon,

For your audit. (pending for parts prices)

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)