

Veron Chen (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Wednesday, 8 December 2021 10:01 AM
To: Veron Chen (LKKAUTO)
Subject: RE: GBH 3200D ---CS/MSG21008920/T1vf3

Dear Veron,

AUDIT CHECK DONE FOR GBH3200D, FOUND PB & SP LABOUR TOO HIGH AND SURVEYOR MARKING NEED TO REVIEW.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 7 December, 2021 5:49 PM
To: Simon Ho (LKKAUTO)
Subject: GBH 3200D ---CS/MSG21008920/T1vf3

Dear Simon

File for audit check.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)