



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008925/Uuf3n2	
			Date: 28/09/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5039B	Veh. Inspected	SLM 9336L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/21/2053	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	25/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	GP53321348	Colour	BLUE
	Odometer	193429 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/45 ZR16	TOURADOR	6 mm
	L/H Front Tyre	205/45 ZR16	TOURADOR	6 mm
	R/H Rear Tyre	205/45 ZR16	TOURADOR	6 mm
	L/H Rear Tyre	205/45 ZR16	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/08/2021	Inspection Date	25/08/2021
	Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	