



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI21008926/Eqc Date: 25/08/2021 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SCA 16P
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM21D204669/C01/TOHHS	Excess (\$)	0.00 1300
	Assign From	ALFRED TOH	Assign Date	25/08/2021
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	23/08/2021	Inspection Date	25/08/2021
	Survey held at	BLK K PANDAN LOOP IND ESTATE, Pandan Loop, #01-12		
	Repairer	GOLDBELL ENGINEERING PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			