Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16 Singapore 079120 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Nadaraja, Deeban Date: 25 Aug 2021

Preliminary Advice

Vehicle No : SJU9886Y **Accident Date** : 19/08/2021

Policy No. Make : AUDI A3

Assignment Date : 25/08/2021 Excess : S\$0.00 Date of Inspection : 24/08/2021 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 17,940.00 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 11,004.00 |
| Check Items (Estimated) | :S\$ | 735.00 |
| Total | :S\$ | 11,739.00 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 92,000.00 COE / PARF Rebate :S\$ 39,002.00

Salvage Value :S\$

Margin for Repair :S\$ 52,998.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir | ndly |
|-------|--|------|
| | let us have your authorisation. | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.