CHIANG/ CHINA

MODEL	HYU-140	CHIANG/ CHINA			
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	]
	REAR BUMPER COVER			\$1,106.00	Cut
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20	
	REAR BUMPER CLIPS		\$2.20	\$22.00	nec
	REAR BUMPER REFLECTOR LH /RH		\$32.00	\$64.00	
	REAR BUMPER REINFORCEMENT			\$428.40	XSVC
	REAR BUMPER UNDER COVER			\$228.00	CATE
1	BOOTLID COVER			\$2,609.80	
1	BOOTLID MOULDING			\$85.0 <b>Q</b>	/50
1	BOOT LID LOCK UPPER			\$114.90	
	REAR TAIL END PANEL			\$526.00	4 . 00
_	REAR PANEL GARNISH				*X SUC
	BOOTLID EMBLEM CRDI			\$52.40	
	1BOOTLID H EMBLEM			\$63.10	nec
1 ~	1 BOOTLID EMBLEM 140			\$52.40	ncc
		7		\$5,480.90	
	20.00%	-		\$1,096.18	-1
	DISCOUNTED TOTAL			\$4,384.72	
					Nec
	1 BOOTLID ADVERTISEMENT			\$100.00	1000
1	I REAR BUMPER ADVERTISEMENT			\$50.00	NIC
	BOOTID COMFORT & TEL NUMBER STICKER	21.00	20	l .	/ /
	1 REVERSE SENSOR	342-	70	\$135.70 <b>\$345.70</b>	
				\$345.70	
	Labour Charge			<b>\$5</b> \$840.00	Varia
	Panel Beating			\$840.00 \$750.00	
1	Spray Painting Charge			\$60.00	
1	Remove/refix reverse sensor			\$60.00	-1
1	Check lighting			\$90.00	
	Tuff Kote TOTAL LABOUR	11.50		\$1,800.00	
	TOTAL DABOOK	1 30		<b>\$2,000.00</b>	7
	ESTIMATE TOTAL			\$6,530.42	2
	ESTIMATE TOTAL	1	ľ	40/0207	7
		· 1	1	4320	qe e
	l a signal inspection of the	a above ve	nicle. The final renair o	uantum will	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will					
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.  LKK Auto Consultants hence notify				_1	
Theyan LAK 24/8/21 1200 15:45		the Repair	er of the following: before/after spray painting		
3 clays WP thevan el thauto. com		<ul> <li>To display</li> </ul>	damaged part(s) during resurve)	,	
		<ul> <li>Parts price</li> </ul>	s are subject to confirmation		
82235769		<ul> <li>No illegal r</li> </ul>	survey is on a "Without Prejudio nodification(s) is allowed	1	
LIS after repair photo		<ul> <li>Supplement</li> </ul>	ntary item(s) must be resurveyed	d <u>and</u> Company	

LIS after repair photo

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: