

# EQUATOR BROTHERHOOD®

## REGISTRATION NO: 53232274J

25 Kaki Bukit Road 4  
Synergy@KB #03-79 Singapore (417800)


Contact: 63846939 / 90113391  
Email: [equator.brotherhood@gmail.com](mailto:equator.brotherhood@gmail.com)

### PRE - REPAIR INSPECTION

**Bike Model:** Yamaha Jupiter MX133

**Bike Plate:** FBG7047J

| S/N | Parts Description                   | Quantity | Unit Price | Amount    |
|-----|-------------------------------------|----------|------------|-----------|
| 1   | Yamaha fairing set (coloured)       | 1        | \$ 400.00  | \$ 400.00 |
| 2   | Yamaha fairing set (matte black)    | 1        | \$ 180.00  | \$ 180.00 |
| 3   | Yamaha exhaust                      | 1        | \$ 420.00  | \$ 420.00 |
| 4   | Yamaha exhaust cover (black)        | 1        | \$ 45.00   | \$ 45.00  |
| 5   | Yamaha exhaust cover (silver)       | 1        | \$ 65.00   | \$ 65.00  |
| 6   | Yamaha exhaust gasket               | 1        | \$ 15.00   | \$ 15.00  |
| 7   | Yamaha foot step bar                | 1        | \$ 65.00   | \$ 65.00  |
| 8   | Yamaha rider footrest (left)        | 1        | \$ 25.00   | \$ 25.00  |
| 9   | Yamaha rider footrest (right)       | 1        | \$ 25.00   | \$ 25.00  |
| 10  | Yamaha rider footrest pin           | 2        | \$ 15.00   | \$ 30.00  |
| 11  | Yamaha rider footrest spring        | 2        | \$ 20.00   | \$ 40.00  |
| 12  | Yamaha pillion foot rest bracket    | 2        | \$ 65.00   | \$ 130.00 |
| 13  | Yamaha pillion foot rest            | 2        | \$ 25.00   | \$ 50.00  |
| 14  | Yamaha pillion foot rest pin        | 2        | \$ 15.00   | \$ 30.00  |
| 15  | Yamaha side stand                   | 1        | \$ 65.00   | \$ 65.00  |
| 16  | Yamaha swingarm                     | 1        | \$ 380.00  | \$ 380.00 |
| 17  | Yamaha swingarm shaft               | 1        | \$ 50.00   | \$ 50.00  |
| 18  | Yamaha swingarm bushing + bearing   | 2        | \$ 25.00   | \$ 50.00  |
| 19  | Yamaha mirror set                   | 2        | \$ 35.00   | \$ 70.00  |
| 20  | Yamaha rear suspension              | 1        | \$ 280.00  | \$ 280.00 |
| 21  | Yamaha clutch lever                 | 1        | \$ 45.00   | \$ 45.00  |
| 22  | Yamaha clutch cable                 | 1        | \$ 45.00   | \$ 45.00  |
| 23  | Yamaha clutch lever holder          | 1        | \$ 45.00   | \$ 45.00  |
| 24  | Yamaha clutch lever holder screw    | 1        | \$ 10.00   | \$ 10.00  |
| 25  | Yamaha clutch cable length adjuster | 1        | \$ 20.00   | \$ 20.00  |



**REGISTRATION NO: 53232274J**

25 Kaki Bukit Road 4  
Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391  
Email: [equator.brotherhood@gmail.com](mailto:equator.brotherhood@gmail.com)

## PRE - REPAIR INSPECTION

**Bike Model:** Yamaha Jupiter MX133

**Bike Plate:** FBG7047J

| S/N | Parts Description                            | Quantity | Unit Price | Amount    |
|-----|----------------------------------------------|----------|------------|-----------|
| 26  | Yamaha gear shifter                          | 1        | \$ 35.00   | \$ 35.00  |
| 27  | Yamaha gear shifter tie rod                  | 1        | \$ 20.00   | \$ 20.00  |
| 28  | Yamaha gear shifter rubber                   | 1        | \$ 20.00   | \$ 20.00  |
| 29  | Yamaha gear shifter arm                      | 1        | \$ 30.00   | \$ 30.00  |
| 30  | Number plate rear                            | 1        | \$ 20.00   | \$ 20.00  |
| 31  | LiquiMoly front brake fluid                  | 1        | \$ 20.00   | \$ 20.00  |
| 32  | LiquiMoly rear brake fluid                   | 1        | \$ 20.00   | \$ 20.00  |
| 33  | Givi box rack                                | 1        | \$ 110.00  | \$ 110.00 |
| 34  | Givi box 42L                                 | 1        | \$ 210.00  | \$ 210.00 |
| 35  | Givi box base plate                          | 1        | \$ 85.00   | \$ 85.00  |
| 36  | Towing 1-trip (Workshop to reporting center) | 1        | \$ 65.00   | \$ 65.00  |
| 37  | Towing 1-trip (Reporting center to workshop) | 1        | \$ 65.00   | \$ 65.00  |
| 38  | Towing 1-trip (TP compound to workshop)      | 1        | \$ 65.00   | \$ 65.00  |
| 39  | Chassis alignment                            | 1        | \$ 480.00  | \$ 480.00 |
| 40  | Labor                                        | 1        | \$ 480.00  | \$ 480.00 |
| 41  | Rear reflector                               | 1        | \$ 25.00   | \$ 25.00  |
| 42  |                                              |          |            | \$ -      |
| 43  |                                              |          |            | \$ -      |
| 44  |                                              |          |            | \$ -      |
| 45  |                                              |          |            | \$ -      |
| 46  |                                              |          |            | \$ -      |
| 47  |                                              |          |            | \$ -      |
| 48  |                                              |          |            | \$ -      |
| 49  |                                              |          |            | \$ -      |
| 50  |                                              |          |            | \$ -      |
| 51  |                                              |          |            | \$ -      |



# EQUATOR BROTHERHOOD®

REGISTRATION NO:53232274J

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: [equator.brotherhood@gmail.com](mailto:equator.brotherhood@gmail.com)

## PRE - REPAIR INSPECTION

Bike Model: Yamaha Jupiter MX133

Bike Plate: FBG7047J

| S/N | Parts Description | Quantity | Unit Price    | Amount      |
|-----|-------------------|----------|---------------|-------------|
| 52  |                   |          | \$ -          | \$ -        |
| 53  |                   |          | \$ -          | \$ -        |
| 54  |                   |          | \$ -          | \$ -        |
| 55  |                   |          | \$ -          | \$ -        |
| 56  |                   |          | \$ -          | \$ -        |
| 57  |                   |          | \$ -          | \$ -        |
| 58  |                   |          | \$ -          | \$ -        |
| 59  |                   |          | \$ -          | \$ -        |
| 60  |                   |          | \$ -          | \$ -        |
| 61  |                   |          | \$ -          | \$ -        |
| 62  |                   |          | \$ -          | \$ -        |
| 63  |                   |          | \$ -          | \$ -        |
| 64  |                   |          | \$ -          | \$ -        |
| 65  |                   |          | \$ -          | \$ -        |
| 66  |                   |          | \$ -          | \$ -        |
| 67  |                   |          | \$ -          | \$ -        |
| 68  |                   |          | \$ -          | \$ -        |
| 69  |                   |          | \$ -          | \$ -        |
| 70  |                   |          | \$ -          | \$ -        |
| 71  |                   |          | \$ -          | \$ -        |
| 72  |                   |          | \$ -          | \$ -        |
| 73  |                   |          | \$ -          | \$ -        |
| 74  |                   |          | \$ -          | \$ -        |
| 75  |                   |          | \$ -          | \$ -        |
| 76  |                   |          | \$ -          | \$ -        |
|     |                   |          | <b>Total:</b> | \$ 4,330.00 |