

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

30/08/2021

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date : 20/08/2021

Estimated repair cost for vehicle no: SLS898J HONDA CIVIC 1.5 TURBO VTIS SR

CHASSIS: MRHFC1660HT000353 (2017)

| S/N | Qty | Items                                  | U/price    | Amount       |
|-----|-----|----------------------------------------|------------|--------------|
| 1   | 1   | BONNET                                 | \$683.50   | \$683.50 +   |
| 2   | 1   | BONNET RUBBER                          | \$31.40    | \$31.40 +    |
| 3   | 1   | BONNET LOCK                            | \$116.30   | \$116.30 +   |
| 4   | 1   | FRONT GRILLE                           | \$114.50   | \$114.50 ✓   |
| 5   | 1   | FRONT GRILLE CHROME                    | \$97.80    | \$97.80 ✓    |
| 6   | 1   | FRONT GRILLE BASE                      | \$185.10   | \$185.10 ✓   |
| 7   | 1   | FRONT GRILLE LOGO                      | \$17.20    | \$17.20 ✓    |
| 8   | 1   | FRONT BUMPER                           | \$579.90   | \$579.90 ✓   |
| 9   | 1   | FRONT BUMPER REINFORCEMENT             | \$394.80   | \$394.80 +   |
| 10  | 1   | FRONT BUMPER SIDE RETAINER             | \$43.60    | \$43.60 +    |
| 11  | 1   | FRONT BUMPER LOWER GRILLE              | \$79.60    | \$79.60 +    |
| 12  | 1   | FRONT BUMPER TOP BEAM                  | \$245.30   | \$245.30 ✓   |
| 13  | 1   | FRONT BUMPER FOG LAMP OUTER GARNISH RH | \$26.30    | \$260.30 +   |
| 14  | 1   | FRONT SUPPORT PANEL                    | \$1,259.10 | \$1,259.10 + |
| 15  | 1   | FRONT SUPPORT PANEL TOP GARNISH        | \$98.60    | \$98.60 +    |
| 16  | 1   | FRONT SUPPORT PANEL SIDE GUIDE GARNISH | \$65.30    | \$65.30 +    |
| 17  | 1   | FRONT HEADLAMP RH                      | \$1,357.90 | \$1,357.90 ✓ |
| 18  | 1   | FRONT HEADLAMP TOP GARNISH RH          | \$20.80    | \$20.80 ✓    |
| 19  | 1   | FRONT HEADLAMP LOWER BRACKET RH        | \$30.50    | \$30.50 +    |

2641.30

2113.04

|             |            |
|-------------|------------|
| TOTAL :     | \$5,681.50 |
| LESS 20 %   | \$1,136.30 |
| SUB-TOTAL : | \$4,545.20 |

| S/N | Qty | ITEMS / SPECIAL NETT                            | U/price       | Amount              |
|-----|-----|-------------------------------------------------|---------------|---------------------|
| 1   | 1   | FRONT BUMPER LOWER LIP <i>new</i>               | \$1,200.00    | \$1,200.00 <i>+</i> |
| 2   | 1   | FRONT GRILLE STICKER <i>new</i>                 | \$160.00      | \$160.00 <i>120</i> |
| 3   | 1   | FRONT BUMPER CLIPS <i>new</i>                   | \$60.00       | \$60.00 <i>30</i>   |
| 4   | 1   | FRONT GRILLE CLIPS <i>new</i>                   | \$50.00       | \$50.00 <i>20</i>   |
| 5   | 1   | FRONT SUPPORT PANEL TOP GARNISG CIPS <i>new</i> | \$50.00       | \$50.00 <i>+</i>    |
| 6   | 1   | FRONT NUMBER PLATE WITH CASING <i>new</i>       | \$60.00       | \$60.00 <i>+</i>    |
|     |     |                                                 | <b>TOTAL:</b> | <b>\$1,580.00</b>   |

170

**TOTAL PARTS : \$6,125.20**

### Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS

580

*350* \$1,200.00  
*200* \$1,000.00  
*30* \$80.00  
*+* \$300.00  
**Subtotal :- \$2,580.00**

**Total:- \$8,705.20**

*Adrian G*  
*w/s 31/08/21.*

*03 Days*

*total 2863.04*

*w/s 23K*

*23K*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: