

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0690/2021/JT  
**DATE** : 25-Aug-21  
**WIP** : 41303

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/8/21**

**YOUR INSURED VEH NO : GN 5282 M**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**3 days - ok - Johnny Boo**

**22-Oct-21**

**OWNER'S NAME** : MR LOW BAK HIANG BUCK  
**ADDRESS** : BLK 6 ST GEORGE'S LANE  
#09-205  
SINGAPORE 320006  
**TELEPHONE** : HP +65 90058855  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1900110620-01  
**VEHICLE NO** : **SMM 4868 P**  
**MODEL CODE** : A5 SB 2.0 TFSI  
**MODEL YEAR** : 28/6/2019  
**ENGINE NO** : CVK 080218  
**CHASSIS NO** : WAUZZZF52KA054222  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 25-Aug-21  
**PLACE OF ACCIDENT** : FOWLIE ROAD AND JOO CHIAT  
ROAD JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 4868 P**

| S/N                         | NATURE OF JOBS                                                                                            |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                           | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.                        | S/N \$ | 360.00               | \$        | <b>360.00</b>                 |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 1,200.00             | \$        | <b>500.00</b>                 |
| 3                           | TO RESPRAY REAR BUMPER.                                                                                   | \$     | 1,000.00             | \$        | <b>550.00</b>                 |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                            | S/N \$ | 192.00               | \$        | <b>192.00</b>                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                           | :      | <b>\$ 2,752.00</b>   | <b>\$</b> | <b>1,602.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 4868 P**

|                             |                                     |     | DAMAGED PARTS & PRICES |         |          |
|-----------------------------|-------------------------------------|-----|------------------------|---------|----------|
| S/N                         | PARTS DESCRIPTION                   | QTY | S/NETT                 | REMARKS |          |
| 1                           | REAR BUMPER                         | 1   | \$ 2,504.00            | \$      | 2,003.20 |
| 2                           | REAR BUMPER FIXING PARTS            | 1   | \$ 165.00              |         |          |
| 3                           | REAR BUMPER SECURING STRIP          | 1   | \$ 223.00              |         |          |
| 4                           | REAR BUMPER CHROME TRIM             | 1   | \$ 1,016.00            | \$      | 812.80   |
| 5                           | REAR BUMPER REFLECTOR - LH / RH     | 2   | \$ 82.00               |         |          |
| 6                           | REAR BUMPER CARRIER                 | 1   | \$ 940.00              |         |          |
| 7                           | REAR BUMPER CARRIER SEAL            | 2   | \$ 28.00               |         |          |
| 8                           | REAR BUMPER GUIDE SECTION - LH / RH | 2   | \$ 46.00               |         |          |
| 9                           | REAR BUMPER SENSOR                  | 2   | TBC                    |         |          |
| 10                          | REAR BUMPER SENSOR SEAL RING        | 4   | \$ 14.00               |         |          |
| 11                          | SUNDRIES                            |     | \$ 200.00              | \$      | 21.60    |
| <b>TOTAL SPARE PARTS</b>    |                                     | :   | \$ 5,218.00            | \$      | 2,837.60 |
| <b>TOTAL LABOUR CHARGES</b> |                                     | :   | \$ 2,752.00            | \$      | 1,602.00 |
| <b>GRAND TOTAL</b>          |                                     | :   | \$ 7,970.00            | \$      | 4,439.60 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 bl-19/10/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT