





# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
Website: www.goldbell.com.sg  
Co Reg No: 196003963G

Page 1 / 3

## ESTIMATE

|                   |                                          |                 |                                             |
|-------------------|------------------------------------------|-----------------|---------------------------------------------|
| Date :            | 30/08/2021                               | Reg No :        | YM7604Y                                     |
| To :              | INDIA INTERNATIONAL INSURANCE<br>PTE LTD | Model :         | NISSAN / MKB37BNHRA                         |
| Attn. :           |                                          | Chassis No :    | MKB37BN00117                                |
| Office / Mobile : |                                          | Engine No :     | J08EUC10275                                 |
| Email Address :   |                                          | Quotation No. : | 140573                                      |
|                   |                                          | Ref. No. :      | GBE/SVC/SALES-HQ/155-2608                   |
| From :            | GOLDBELL ENGINEERING PTE LTD             | D.O.A. :        | 26/08/2021                                  |
| Attn. :           | CATHERINECHONGKL                         | Policy No. :    | DMCVSNW00042902100                          |
| Office / Mobile : |                                          | Claim Type :    | TP CLAIM - INDIA<br>INTERNATIONAL INSURANCE |
| Email / Fax No. : | CatherineChongKL@goldbell.com.sg         | Workshop :      | 8 TUAS AVE 18                               |


| S/N | Part No | Description                           | Qty | U/Price  | %   | Net Price | Ext Price |
|-----|---------|---------------------------------------|-----|----------|-----|-----------|-----------|
| 1   |         | FRONT WINDSCREEN / BR                 | 1   | 1,600.00 | -10 | 1,440.00  | 1,440.00  |
| 2   |         | FRONT WINDSCREEN MOULDING / HPC       | 1   | 685.33   | -10 | 616.80    | 616.80    |
| 3   |         | FRONT CORNER PANEL RH / DD            | 1   | 1,218.02 | -10 | 1,096.22  | 1,096.22  |
| 4   |         | FRONT WIPER PANEL / DD                | 1   | 1,848.61 | -10 | 1,663.75  | 1,663.75  |
| 5   |         | FRONT STEP GARNISH RH / DD            | 1   | 312.59   | -10 | 281.33    | 281.33    |
| 6   |         | FRONT STEP RH / BR                    | 2   | 385.22   | -10 | 346.70    | 693.40    |
| 7   |         | FRONT FENDER RH (Wheel arch) / DD     | 1   | 743.45   | -10 | 669.11    | 669.11    |
| 8   |         | FRONT BUMPER / DD                     | 1   | 1,916.75 | -10 | 1,725.08  | 1,725.08  |
| 9   |         | FRONT BUMPER STAY RH ?                | 1   | 425.05   | -10 | 382.55    | 382.55    |
| 10  |         | FRONT PANEL CAB x R                   | 1   | 2,857.70 | -10 | 2,571.93  | 2,571.93  |
| 11  |         | FRONT PILLAR RH x R                   | 1   | 2,630.59 | -10 | 2,367.53  | 2,367.53  |
| 12  |         | FRONT DOOR ASSY RH / DD               | 1   | 2,047.96 | -10 | 1,843.16  | 1,843.16  |
| 13  |         | FRONT DOOR WINDOW GLASS RUNCHANNEL ?  | 1   | 491.82   | -10 | 442.64    | 442.64    |
| 14  |         | FRONT DOOR UPPER HINGE RH / BT        | 1   | 453.44   | -10 | 408.10    | 408.10    |
| 15  |         | FRONT DOOR LOWER HINGE RH / BT        | 1   | 453.44   | -10 | 408.10    | 408.10    |
| 16  |         | FRONT DOOR OUTSIDE HANDLE RH / BR     | 1   | 207.57   | -10 | 186.81    | 186.81    |
| 17  |         | FRONT DOOR REGULATOR ASSY RH ?        | 1   | 363.78   | -10 | 327.40    | 327.40    |
| 18  |         | FRONT DOOR INSIDE HANDLE RH ?         | 1   | 70.40    | -10 | 63.36     | 63.36     |
| 19  |         | FRONT DOOR LATCH & ACTUATOR RH ?      | 1   | 1,200.00 | -10 | 1,080.00  | 1,080.00  |
| 20  |         | FRONT DOOR TRIM RH                    | 1   | 1,089.85 | -10 | 980.86    | 980.86    |
| 21  |         | SIDE MIRROR RR VIEW RH x              | 1   | 128.00   | -10 | 115.20    | 115.20    |
| 22  |         | SIDE MIRROR STAY RH / BT              | 1   | 698.58   | -10 | 628.72    | 628.72    |
| 23  |         | FRONT WHEEL HOUSE COVER RH / TN       | 1   | 377.90   | -10 | 340.11    | 340.11    |
| 24  |         | FR WHEEL HOUSE SPLASH SHIELD LWR / TN | 1   | 161.86   | -10 | 145.67    | 145.67    |
| 25  |         | APRON RH                              |     |          |     |           |           |
| 26  |         | HEADLAMP ASSY RH ?                    | 1   | 983.85   | -10 | 885.47    | 885.47    |
| 27  |         | FOG LAMP RH                           | 1   | 291.57   | -10 | 262.41    | 262.41    |
| 28  |         | FRONT TURN SIGNAL LAMP RH / BR        | 1   | 210.78   | -10 | 189.70    | 189.70    |
| 29  |         | FRONT SIDE TURN SIGNAL LAMP RH / BR   | 1   | 77.42    | -10 | 69.68     | 69.68     |
|     |         | BACK OUTER PANEL RH / DD              | 1   | 1,317.91 | -10 | 1,186.12  | 1,186.12  |

PARTS TOTAL :

23,071.21

**FUSO AIRMAN.**

**bizSAFE**  
ST & R





# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

## GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
Website: www.goldbell.com.sg  
Co Reg No: 198003963G

Page 2 / 3

### ESTIMATE

|                   |                                       |                 |                                          |
|-------------------|---------------------------------------|-----------------|------------------------------------------|
| Date :            | 30/08/2021                            | Reg No :        | YM7604Y                                  |
| To :              | INDIA INTERNATIONAL INSURANCE PTE LTD | Model :         | NISSAN / MKB37BNHRA                      |
| Attn. :           |                                       | Chassis No :    | MKB37BN00117                             |
| Office / Mobile : |                                       | Engine No :     | J08EUC10275                              |
| Email Address :   |                                       | Quotation No. : | 140573                                   |
|                   |                                       | Ref. No. :      | GBE/SVC/SALES-HQ/155-2608                |
| From :            | GOLDBELL ENGINEERING PTE LTD          | D.O.A. :        | 26/08/2021                               |
| Attn. :           | CATHERINECHONGKL                      | Policy No. :    | DMCVSNW00042902100                       |
| Office / Mobile : |                                       | Claim Type :    | TP CLAIM - INDIA INTERNATIONAL INSURANCE |
| Email / Fax No. : | CatherineChongKL@goldbell.com.sg      | Workshop :      | 8 TUAS AVE 18                            |

### SPECIAL NETT ITEMS

|   |                                 |   |         |
|---|---------------------------------|---|---------|
| 1 | IU BRACKET / <i>nk</i>          | 1 | 25.00   |
| 2 | WINDSCREEN SEALANT / <i>nk</i>  | 2 | 50.00   |
| 3 | FRONT NUMBER PLATE X            | 1 | 25.00   |
| 4 | COMPANY STICKER / <i>nk</i>     | 1 | 500.00  |
| 5 | UD LOGO / <i>MIS</i>            | 1 | 30.00   |
| 6 | FRONT RIM RH / <i>BT</i>        | 1 | 250.00  |
| 7 | FRONT TYRE RH / <i>TN (50%)</i> | 1 | 180.00  |
| 8 | SIDE STEP UPPER RH / <i>R</i>   | 1 | 1200.00 |
| 9 | WOODEN DECK MIDDLE HOLDER RH    | 1 | 500.00  |

PARTS TOTAL: 2760.00

### LABOUR CHARGES

|   |                                                                                     |      |         |
|---|-------------------------------------------------------------------------------------|------|---------|
| 1 | REMOVE AND REPAIR SIDE WOODEN DECK                                                  | X    | 1300.00 |
| 2 | REMOVE AND REPAIR LOWER SIDE STEP RH                                                | 400  | 700.00  |
| 3 | RE-ALIGN CABIN HEAD (photo)                                                         | 600  | 700.00  |
| 4 | TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC | 3600 | 4000.00 |
| 5 | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC                                        | 2450 | 2500.00 |

LABOUR TOTAL : 9,200.00

SUB-TOTAL : 35,031.21

GST @ 7% for \$ 35,031.21 2,452.18

GRAND TOTAL (S\$) : 37,483.39



AIRMAN.





# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
Website: www.goldbell.com.sg  
Co Reg No: 198003963G

Page 3 / 3

## ESTIMATE

|                   |                                          |                 |                                             |
|-------------------|------------------------------------------|-----------------|---------------------------------------------|
| Date :            | 30/08/2021                               | Reg No :        | YM7604Y                                     |
| To :              | INDIA INTERNATIONAL INSURANCE<br>PTE LTD | Model :         | NISSAN / MKB37BNHRA                         |
| Attn. :           |                                          | Chassis No :    | MKB37BN00117                                |
| Office / Mobile : |                                          | Engine No :     | J08EUC10275                                 |
| Email Address :   |                                          | Quotation No. : | 140573                                      |
|                   |                                          | Ref. No. :      | GBE/SVC/SALES-HQ/155-2608                   |
|                   |                                          | D.O.A. :        | 26/08/2021                                  |
| From :            | GOLDBELL ENGINEERING PTE LTD             | Policy No. :    | DMCVSNW00042902100                          |
| Attn. :           | CATHERINECHONGKL                         | Claim Type :    | TP CLAIM - INDIA<br>INTERNATIONAL INSURANCE |
| Office / Mobile : |                                          | Workshop :      | 8 TUAS AVE 18                               |
| Email / Fax No. : | CatherineChongKL@goldbell.com.sg         |                 |                                             |

PREPARED BY : CATHERINECHONGKL

DATE / TIME :

7/9/21, 12.30 pm

SURVEYOR :

Steve

MOBILE NO :

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE :

PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY :

BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

REMARKS :

WHL PL  
15 dys  
M AL sy

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**FUSO**

**AIRMAN.**

**bisSAFE**  
ST & R

