



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3076
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg No. 198003563G

Page 1 / 3

ESTIMATE

Date : 30/08/2021
To : INDIA INTERNATIONAL INSURANCE
PTE LTD

Attn. :

Office / Mobile :

Email Address :

From : GOLDBELL ENGINEERING PTE LTD

Attn. : CATHERINECHONGKL

Office / Mobile :

Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No : YM7604Y

Model : NISSAN / MKB37BNHRA

Chassis No : MKB37BN00117

Engine No : J08EUC10275

Quotation No. : 140573

Ref. No. : GBE/SVC/SALES-HQ/155-2608

D.O.A. : 26/08/2021

Policy No. : DMCVSNW00042902100

Claim Type : TP CLAIM - INDIA
INTERNATIONAL INSURANCE

Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT WINDSCREEN / BR	1	1,600.00	-10	1,440.00	1,440.00
2		FRONT WINDSCREEN MOULDING / MP	1	685.33	-10	616.80	616.80
3		FRONT CORNER PANEL RH / DD	1	1,218.02	-10	1,096.22	1,096.22
4		FRONT WIPER PANEL / DD	1	1,848.61	-10	1,663.75	1,663.75
5		FRONT STEP GARNISH RH / DD	1	312.59	-10	281.33	281.33
6		FRONT STEP RH / BR	2	385.22	-10	346.70	693.40
7		FRONT FENDER RH (LWR arch) / DD	1	743.45	-10	669.11	669.11
8		FRONT BUMPER / DD	1	1,916.75	-10	1,725.08	1,725.08
9		FRONT BUMPER STAY RH ? XNN	1	425.05	-10	382.55	382.55
10		FRONT PANEL CAB X R	1	2,857.70	-10	2,571.93	2,571.93
11		FRONT PILLAR RH X R	1	2,630.59	-10	2,367.53	2,367.53
12		FRONT DOOR ASSY RH / DD	1	2,047.96	-10	1,843.16	1,843.16
13		FRONT DOOR WINDOW GLASS RUNCHANNEL ? XNN	1	491.82	-10	442.64	442.64
14		FRONT DOOR UPPER HINGE RH / BT	1	453.44	-10	408.10	408.10
15		FRONT DOOR LOWER HINGE RH / BT	1	453.44	-10	408.10	408.10
16		FRONT DOOR OUTSIDE HANDLE RH / BR	1	207.57	-10	186.81	186.81
17		FRONT DOOR REGULATOR ASSY RH ? XNN	1	363.78	-10	327.40	327.40
18		FRONT DOOR INSIDE HANDLE RH ? XNN	1	70.40	-10	63.36	63.36
19		FRONT DOOR LATCH & ACTUATOR RH ? XNN	1	1,200.00	-10	1,080.00	1,080.00
20		FRONT DOOR TRIM RH XNN	1	1,089.85	-10	980.86	980.86
21		SIDE MIRROR RR VIEW RH X NN	1	128.00	-10	115.20	115.20
22		SIDE MIRROR STAY RH / BT	1	698.58	-10	628.72	628.72
23		FRONT WHEEL HOUSE COVER RH / TN	1	377.90	-10	340.11	340.11
24		FR WHEEL HOUSE SPLASH SHIELD LWR / TN	1	161.86	-10	145.67	145.67
25		APRON RH					
26		HEADLAMP ASSY RH XNN	1	983.85	-10	885.47	885.47
27		FOG LAMP RH / BR	1	291.57	-10	262.41	262.41
28		FRONT TURN SIGNAL LAMP RH / BR	1	210.78	-10	189.70	189.70
29		FRONT SIDE TURN SIGNAL LAMP RH / BR	1	77.42	-10	69.68	69.68
		BACK OUTER PANEL RH / DD	1	1,317.91	-10	1,186.12	1,186.12

PARTS TOTAL :

23,071.21



AIRMAN.





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638992 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638992 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg No. 15602263G

Page 2 / 3

ESTIMATE

Date	: 30/08/2021	Reg No	: YM7604Y
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: NISSAN / MKB37BNHRA
Attn.	:	Chassis No	: MKB37BN00117
Office / Mobile	:	Engine No	: J08EUC10275
Email Address	:	Quotation No.	: 140573
		Ref. No.	: GBE/SVC/SALES-HQ/155-2608
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 26/08/2021
Attn.	: CATHERINECHONGKL	Policy No.	: DMCVSNW00042902100
Office / Mobile	:	Claim Type	: TP CLAIM - INDIA INTERNATIONAL INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

SPECIAL NETT ITEMS

1	IU BRACKET	1	25.00
2	WINDSCREEN SEALANT	2	50.00
3	FRONT NUMBER PLATE	1	25.00
4	COMPANY STICKER	1	500.00
5	UD LOGO	1	30.00
6	FRONT RIM RH	1	250.00
7	FRONT TYRE RH	1	180.00
8	SIDE STEP UPPER RH	1	1200.00
9	WOODEN DECK MIDDLE HOLDER RH	1	500.00
PARTS TOTAL:			2760.00

LABOUR CHARGES

1	REMOVE AND REPAIR SIDE WOODEN DECK	1300.00
2	REMOVE AND REPAIR LOWER SIDE STEP RH	700.00
3	RE-ALIGN CABIN HEAD	700.00
4	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	4000.00
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	2500.00
LABOUR TOTAL :		9,200.00
SUB-TOTAL :		35,031.21
GST @ 7% for \$ 35,031.21		2,452.18
GRAND TOTAL (S\$) :		37,483.39



AIRMAN.



ESTIMATE

Date :	30/08/2021	Reg No :	YM7604Y
To :	INDIA INTERNATIONAL INSURANCE PTE LTD	Model :	NISSAN / MKB37BNHRA
Attn. :		Chassis No :	MKB37BN00117
Office / Mobile :		Engine No :	J08EUC10275
Email Address :		Quotation No. :	140573
		Ref. No. :	GBE/SVC/SALES-HQ/155-2608
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	26/08/2021
Attn. :	CATHERINECHONGKL	Policy No. :	DMCVSNW00042902100
Office / Mobile :		Claim Type :	TP CLAIM - INDIA INTERNATIONAL INSURANCE
Email / Fax No. :	CatherineChongKL@goldbell.com.sg	Workshop :	8 TUAS AVE 18

PREPARED BY : CATHERINECHONGKL

DATE / TIME :

7/9/21, 12.30 pm

SURVEYOR :

Steve

MOBILE NO :

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE :

PART-BY-PART / LUMPSUM

AUTHORISATION :

AUTHORISED / NOT AUTHORISED

RE-SURVEY :

BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

REMARKS :

W/L PL
15 dys
M AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: