




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDING SINGAPORE 068909			Ref: CS3/UOI21009023/Bvf3e2 Date: 10/09/2021 Code: UOI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLL 5408U	Veh. Inspected	SKH 3679A
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D16472109	Excess (\$)	0.00
	Assign From	KATIE LEE	Assign Date	27/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520I 2.0	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WBAXG120X0DX51576	Colour	BLACK
	Odometer	212612 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	DUNLOP	5 mm
	L/H Front Tyre	225/55 R17	DUNLOP	5 mm
	R/H Rear Tyre	225/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	225/55 R17	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	25/08/2021	Inspect Date / Time	27/08/2021 (04:16 PM)
	Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days

Report Ref No. CS3/UOI21009023/Bvf3e2

Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.