

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	Re	ef:	CS/CTI21009024/Avc		
	3 ANSON ROAD # SPRINGLEAF TOV	Da	ate:	27/08/2021		
			Co	ode:	СТІ	
1.	I. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SDY 1888U	Veh. Inspected		SMP 710X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D204756/C02/SDY1888 U/TANKW	Excess (\$)		0.00	
	Assign From	TAN KIAN WEI BILLY	Assign Date		27/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	dometer - Steering				
	Brakes	rakes Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	24/08/2021	Inspection Date		27/08/2021	
	Survey held at	2020 SPRAY PAINTING PTE LTD				
		53 UBI AVENUE 1, #05-15, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934				
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						