

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 59309**
Date Estimated : **26/08/2021**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Gene Phay Mia Young (Peng MiaoYang)
38 Mount Vernon Road. (S)368059
Bartley Ridge
#13-28
SINGAPORE 368059

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX288C	WBA5F32000FJ140	25/06/2020	320i Sedan	20023

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# REAR LH TRIM PANEL	75.25	1.00	0.00	75.25 ✓ BR
# REAR RH TRIM PANEL	75.25	1.00	0.00	75.25 ✓ BR
# REAR RH LIGHT IN TRUNK LID		1.00	0.00	390.25 ✓ BR

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts : 540.75